



#3

Master bedroom
Sash to be replaced

EZP25828688HS2_6/5/2018_4:56:07-AM

#2

Corried area
that wood is rotted
; need repair -

finger can poke
through



EZP25828688HS2_6/5/2018_4:56:07-AM

#1

Dining Rm
Windows that has
wood frame that
wood is rotted -
will be repaired &
painted with same
color as shown in
picture

(this is on Northside /
back side of house)

EZP25828688HS2_6/5/2018_4:56:07-AM



#6

Kitchen Sashes;
transom require
re placement

Sashes 2 on the
left

transoms - the two
end will be replaced
not the middle one

EZP25920668H62_6/5/2018_4:56:07-AM

#5


Master bed room
Sash with wood
Rot

EZP25920668H62_6/5/2018_4:56:07-AM

#4

Master bed room
Sash with
wood Rot

EZP25920668H62_6/5/2018_4:56:07-AM



#9

Kitchen encasement
sash with rot

EZP25828688HS2_6/5/2018_4:56:07_PM

#8


Kitchen encasement
sash with rot

EZP25828688HS2_6/5/2018_4:56:07_PM

#7 -

Kitchen windows
closer picture

EZP25828688HS2_6/5/2018_4:56:07_PM



#12

Kitchen encasement
Sash with rot

EZP25828688HS2_6/5/2018_4:56:07_AM

#11


Kitchen encasement
Sash with rot

EZP25828688HS2_6/5/2018_4:56:07_AM

#10

Kitchen encasement
Sash with rot

EZP25828688HS2_6/5/2018_4:56:07_AM



#15

Transom to be
replaced due to
rot - finger poked
through bottom of
sash

EZP25928698HS2_6/5/2018_4:56:07-AM

#14


Kitchen window
frame - wood
rot to be repaired

EZP25928698HS2_6/5/2018_4:56:07-AM

#13

Kitchen encasement
sash with rot

EZP25928698HS2_6/5/2018_4:56:07-AM



#16 Transom to be
replace due to rot
finger joined through
bottom 7 inch

EZP25828682H52.6/5/2018.4:56:02 PM