## 2019

## **FC Elliot Porch Restoration**



501 Dunbar Avenue -Porch roof replacement -Soffit & facia repairs -Installation of chimney liner Issued: 12/3/2019

## Photos of Damaged Areas



Detail from roof line.

Missing gutter has caused damage to siding, including rot. Entire section from window to blue molding needs to be replaced.

New gutter and spout will be added to prevent future damage.

Note "tenting" of rubber roof line below. Leaking apparent from below porch roof.



Evidence of porch roof water damage. Note pealing along gutter line, tenting, rolling, bumps.

Peeling of roof from architectural features.

Improper flashing along roof line.





Detail photo. Evidence of underlay rot. Peeling of roof surface.



## Various examples of soffit and fascia damage.





501 Dunbar Porch Restoration



Full exterior porch view.