


this
window





#3

Master bedroom
Sash to be replaced

EZP2582868H92_6/5/2018_4:56:07_PM

#2

Circled area that wood is rotted & need repair - finger can poke through

EZP2582868H92_6/5/2018_4:56:07_PM


#1


Dining Rm
Windows that has wood frame that wood is rotted - will be repaired & painted with same color as shown in picture

(this is on Northside / back side of house)

EZP2582868H92_6/5/2018_4:56:07_PM








#6

Kitchen Sashes ; transom require replacement


Sashes 2 on the left

transoms - the two end will be replaced not the middle one




#5

Master bedroom Sash with wood Rot




#4

Master bedroom sash with wood Rot












#9
Kitchen encasement sash with rot




#8
Kitchen encasement sash with rot




#7 -
Kitchen windows closer picture











#12

Kitchen encasement
Sash with rot




#11

Kitchen encasement
Sash with rot




#10

Kitchen encasement
Sash with rot











#15

Transom to be replaced due to rot - finger poked through bottom of sash




#14


Kitchen window frame & wood rot to be repaired



#13

Kitchen encasement sash with rot





#10 Transom to be replaced due to Rot. Paint peeled through bottom 2 sash

EZP2582868BH52 6/5/2018 4:56:00 PM