TO THE BOARD OF PUBLIC WORKS CITY OF WAUKESHA, WISCONSIN

Periodical estimate for Partial Payment No. 5 to Willkomm Excavating & Grading, Inc., 17108 County Line Rd., Union Grove 53182 for Windsor Dr. and S. Charles St. Utility and Street Improvements (Concrete Alternate).

Contract No. 3857 3/4/2014 \$ 865,259.40

Item No	Quantity	Description		Cost	Per Unit	Amount
1	1,274	8-Inch Water Main and Fittings	@	\$76.20	Lin. Ft.	\$97,078.80
2	3	Furnish and Install 8-Inch Gate Valves	@	\$1,900.00	Each	\$5,700.00
3	3	Furnish and Install Hydrant Assembly	@	\$6,630.00	Each	\$19,890.00
4	2	Connect 1-Inch Copper Service Lateral (SL1)	@	\$740.00	Each	\$1,480.00
5	5	Connect 1-Inch Service Lateral (SL2)	@	\$950.00	Each	\$4,750.00
6	6	Connect Service Lateral (SL3)	@	\$1,560.00	Each	\$9,360.00
7	6	Connect Service Lateral (SL4)	@	\$2,220.00	Each	\$13,320.00
8	8	Connect Service Lateral (SL5)	@	\$2,200.00	Each	\$17,600.00
9	1	Connect Service Lateral (SL6)	@	\$2,120.00	Each	\$2,120.00
10	1	Connect 11/4-Inch Copper Service Lateral (SL7)	@	\$1,120.00	Each	\$1,120.00
11	1	Connect Service Lateral (SL8)	@	\$2,150.00	Each	\$2,150.00
12	3	Abandon Existing Hydrants	@	\$810.00	Each	\$2,430.00
13	1.00	Abandon Valve Boxes & Manholes	@	\$1,260.00	Lump Sum	\$1,260.00
14	490	8-Inch Sanitary Sewer Lining	@	\$28.10	Lin. Ft.	\$13,769.00
15	8	Lateral Reinstatements	@	\$132.00	Each	\$1,056.00
16	2	Lateral Location from the House	@	\$263.00	Each	\$526.00
17	15	Installation of Cleanout	@	\$1,420.00	Each	\$21,300.00
18	15	Lateral Cleaning and Pre-Lining Inspection	@	\$210.00	Each	\$3,150.00
19	15	Lateral Lining and Post-Lining Inspection	@	\$3,200.00	Each	\$48,000.00
20	0	Lateral Lining Beyond 40-Ft.	@	\$48.00	Lin. Ft.	\$0.00
21	0	Lateral Repair	@	\$3,500.00	Each	\$0.00
22	1	Lateral Replacement by Open Cut	@	\$2,640.00	Each	\$2,640.00
23	0	Bench / Invert / Trough Work Minor	@	\$885.00	Each	\$0.00
24	4	Sanitary Manhole Chimney Replacement	@	\$1,280.00	Each	\$5,120.00
25	4	Sanitary Manhole Internal Chimney Seal	@	\$425.00	Each	\$1,700.00
26	1,060	Pre-Paving Sanitary Sewer Main Line Televising	@	\$1.90	Lin. Ft.	\$2,014.00
27	20	Pre-Paving Sanitary Sewer Lateral Televising	@	\$185.00	Each	\$3,700.00
28	0	Slurry Backfill	@	\$63.00	Cu. Yd.	\$0.00
	1.500	Non Metallic Conduit, Street Light, Polyethylene	@			
29	1,500	Duct, 2-Inch		\$16.20	Lin, Ft.	\$24,300.00
30	0	Street Light Pull Boxes, 15-Inch x 30-Inch	@	\$670.00	Each	\$0.00
31	5	Post Top Roadway Lighting Unit Concrete Base	@	\$790.00	Each	\$3,950.00
32	0	No. 4 AWG (Black)	@	\$1.40	Lin. Ft.	\$0.00
33	0	No. 4 AWG (Red)	@	\$1.40	Lin, Ft.	\$0.00
34	0	No. 4 AWG (White)	@	\$1.40	Lin. Ft.	\$0.00
35	0	No. 6 AWG (Green)	@	\$1.15	Lin. Ft.	\$0.00
36	0.8	Traffic Control	@	\$15,800.00	Lump Sum	\$12,640.00
37	80	Sawcutting at Pavement Limits	@	\$2.50	Lin. Ft.	\$200.00
38	2,500	Concrete Curb and Gutter Removal	@	\$2.40	Lin, Ft,	\$6,000.00
39	3,800	Pavement Removal	@	\$13.60	Sq. Yd.	\$51,680.00
	æ		€.	255533	3554 8 5 170769	

1	40	4,100	Walk and Drive Approach Removal	@	\$1.00	Sq. Ft.	\$4,100.00
3	41	0	• •	@	\$11.70		\$0.00
3	42	5,334.73	11/4-Inch Crushed Stone Backfill (Includes Undercut)	@	\$20.90	Ton	\$111,495.86
Section Sect	43	0	3-Inch Crushed Stone Backfill (Includes Undercut)	@	\$20.70	Ton	
18-Inch Combination Concrete Curb and Gutter	44	1,400	Shaping and Grading of Roadway Base	@	\$11.60	Lin. Ft.	\$16,240.00
47 3,100 30-Inch Combination Concrete Curb and Gutter @ \$13.10 Lin. Ft. \$40,610.00 48 2,200 New 4-Inch Concrete Walk & Curb Ramps @ \$3.60 Sq. Ft. \$7,920.00 49 700 New 6-Inch Concrete Walk & Drive Approach @ \$4.50 Sq. Ft. \$3,150.00 50 1,000 New 7-Inch Concrete Walk & Drive Approach @ \$5.00 Sq. Ft. \$5,000.00 51 0 New Concrete Steps @ \$42.00 Lin. Ft. \$0.00 52 64 Detectable Warning Surface (8 Ramps) @ \$36.80 Sq. Ft. \$2,355.20 53 0 Concrete Curb - Pedestrian @ \$26.30 Lin. Ft. \$0.00 54 4,000 8-Inch Non-Reinforced Concrete Pavement @ \$27.90 Ton \$111,600.00 55 0 Intentionally Left Blank @ Ton \$0.00 Ton \$0.00 56 0 4-Inch HMA Driveway @ \$5.00 \$q. Ft. \$0.00 57 0 Removal and Replacement of Salvaged Carriage Walk @ Stone \$12.70 \$q. Ft. \$0.00 58 0 Topsoil and Sod (Includes Stripping) @ \$7.40 \$q. Ft. \$0.00 59 0 Silt Fence, Delivered, Installed and Maintained @ \$11.00	45	6,000	Geotextile Fabric, Type SAS	@	\$1.90	Sq. Yd.	\$11,400.00
48 2,200 New 4-Inch Concrete Walk & Curb Ramps @ \$3.60 Sq. Ft. \$7,920.00 49 700 New 6-Inch Concrete Walk & Drive Approach @ \$4.50 Sq. Ft. \$3,150.00 50 1,000 New 7-Inch Concrete Walk & Drive Approach @ \$5.00 Sq. Ft. \$5,000.00 51 0 New Concrete Steps @ \$42.00 Lin. Ft. \$0.00 52 64 Detectable Warning Surface (8 Ramps) @ \$36.80 Sq. Ft. \$2,355.20 53 0 Concrete Curb - Pedestrian @ \$26.30 Lin. Ft. \$0.00 54 4,000 8-Inch Non-Reinforced Concrete Pavement @ \$27.90 Ton \$111,600.00 55 0 Intentionally Left Blank @ Ton \$111,600.00 56 0 4-Inch HMA Driveway @ \$5.00 Sq. Ft. \$0.00 57 0 Removal and Replacement of Salvaged Carriage Walk @ \$12.70 Sq. Ft. \$0.00 59	46	0	18-Inch Combination Concrete Curb and Gutter	@	\$23.70	Lin. Ft.	\$0.00
49 700 New 6-Inch Concrete Walk & Drive Approach @ \$4.50 \$G, Ft. \$3,150.00 50 1,000 New 7-Inch Concrete Walk & Drive Approach @ \$5.00 \$G, Ft. \$5,000.00 51 0 New Concrete Steps @ \$42.00 Lin. Ft. \$0.00 52 64 Detectable Warning Surface (8 Ramps) @ \$36.80 \$G, Ft. \$2,355.20 53 0 Concrete Curb - Pedestrian @ \$26.30 Lin. Ft. \$0.00 54 4,000 8-Inch Non-Reinforced Concrete Pavement @ \$27.90 Ton \$111,600.00 55 0 Intentionally Left Blank @ Ton \$0.00 56 0 4-Inch HMA Driveway @ \$5.00 \$q. Ft. \$0.00 57 0 Removal and Replacement of Salvaged Carriage Walk @ \$12.70 \$q. Ft. \$0.00 58 0 Topsoil and Sod (Includes Stripping) @ \$7.40 \$q. Yd. \$0.00 59 0	47	3,100	30-Inch Combination Concrete Curb and Gutter	@	\$13.10	Lin. Ft.	\$40,610,00
1,000 New 7-Inch Concrete Walk & Drive Approach \$5.00 \$5.00 \$Q. Ft. \$5,000.00	48	2,200	New 4-Inch Concrete Walk & Curb Ramps	@	\$3.60	Sq. Ft.	\$7,920.00
51 0 New Concrete Steps @ \$42.00 Lin. Ft. \$0.00 52 64 Detectable Warning Surface (8 Ramps) @ \$36.80 Sq. Ft. \$2,355.20 53 0 Concrete Curb - Pedestrian @ \$26.30 Lin. Ft. \$0.00 54 4,000 8-Inch Non-Reinforced Concrete Pavement @ \$27.90 Ton \$111,600.00 55 0 Intentionally Left Blank @ Ton \$0.00 56 0 4-Inch HMA Driveway @ \$5.00 Sq. Ft. \$0.00 57 0 Removal and Replacement of Salvaged Carriage Walk @ \$12.70 Sq. Ft. \$0.00 58 0 Topsoil and Sod (Includes Stripping) @ \$7.40 Sq. Yd. \$0.00 59 0 Silt Fence, Delivered, Installed and Maintained \$5.10 Lin. Ft. \$0.00 60 6 Straw Bales Delivered, Installed and Maintained \$11.00 Each \$66.00 61 5 Filter Fabric Inlet Protection	49	700	New 6-Inch Concrete Walk & Drive Approach	@	\$4.50	Sq. Ft.	\$3,150.00
52 64 Detectable Warning Surface (8 Ramps) @ \$36.80 Sq. Ft. \$2,355.20 53 0 Concrete Curb - Pedestrian @ \$26.30 Lin. Ft. \$0.00 54 4,000 8-Inch Non-Reinforced Concrete Pavement @ \$27.90 Ton \$111,600.00 55 0 Intentionally Left Blank @ Ton \$0.00 56 0 4-Inch HMA Driveway @ \$5.00 Sq. Ft. \$0.00 57 0 Removal and Replacement of Salvaged Carriage Walk Stone \$12.70 Sq. Ft. \$0.00 58 0 Topsoil and Sod (Includes Stripping) @ \$7.40 Sq. Yd. \$0.00 59 0 Silt Fence, Delivered, Installed and Maintained @ \$5.10 Lin. Ft. \$0.00 60 6 Straw Bales Delivered, Installed and Maintained \$11.00 Each \$250.00 61 5 Filter Fabric Inlet Protection @ \$50.00 Each \$694,190.86 62 0 Extra Bag	50	1,000	New 7-Inch Concrete Walk & Drive Approach	@	\$5.00	Sq. Ft.	\$5,000.00
53 0 Concrete Curb - Pedestrian @ \$26.30 Lin. Ft. \$0.00 54 4,000 8-Inch Non-Reinforced Concrete Pavement @ \$27.90 Ton \$111,600.00 55 0 Intentionally Left Blank @ \$5.00 Sq. Ft. \$0.00 56 0 4-Inch HMA Driveway @ \$5.00 Sq. Ft. \$0.00 57 0 Removal and Replacement of Salvaged Carriage Walk @ \$12.70 Sq. Ft. \$0.00 58 0 Topsoil and Sod (Includes Stripping) @ \$7.40 Sq. Yd. \$0.00 59 0 Silt Fence, Delivered, Installed and Maintained @ \$5.10 Lin. Ft. \$0.00 60 6 Straw Bales Delivered, Installed and Maintained \$11.00 Each \$250.00 61 5 Filter Fabric Inlet Protection @ \$50.00 Each \$0.00 62 0 Extra Bags of Cement for High-Early-Strength Concrete \$16.00 Each \$0.00 8 S	51	0	New Concrete Steps	@	\$42.00	Lin. Ft.	\$0.00
54 4,000 8-Inch Non-Reinforced Concrete Pavement © \$27.90 Ton \$111,600.00 55 0 Intentionally Left Blank © Ton \$0.00 56 0 4-Inch HMA Driveway © \$5.00 \$q. Ft. \$0.00 57 0 Removal and Replacement of Salvaged Carriage Walk Stone \$12.70 \$q. Ft. \$0.00 58 0 Topsoil and Sod (Includes Stripping) © \$7.40 \$q. Yd. \$0.00 59 0 Silt Fence, Delivered, Installed and Maintained © \$5.10 Lin. Ft. \$0.00 60 6 Straw Bales Delivered, Installed and Maintained © \$11.00 Each \$66.00 61 5 Filter Fabric Inlet Protection @ \$50.00 Each \$250.00 62 0 Extra Bags of Cement for High-Early-Strength % \$16.00 Each \$0.00 62 0 Extra Bags of Cement for High-Early-Strength % \$16.00 Each \$0.00 62 0 Extra Bags of Cement for High-Early-Strength % \$10.00 Each	52	64	Detectable Warning Surface (8 Ramps)	@	\$36.80	Sq. Ft.	\$2,355.20
Standard Reinfect Content of Co	53	0	Concrete Curb - Pedestrian	@	\$26.30	Lin. Ft.	\$0.00
56 0 4-Inch HMA Driveway @ \$5.00 Sq. Ft. \$0.00 57 0 Removal and Replacement of Salvaged Carriage Walk Stone \$12.70 Sq. Ft. \$0.00 58 0 Topsoil and Sod (Includes Stripping) @ \$7.40 Sq. Yd. \$0.00 59 0 Silt Fence, Delivered, Installed and Maintained @ \$5.10 Lin. Ft. \$0.00 60 6 Straw Bales Delivered, Installed and Maintained @ \$11.00 Each \$66.00 61 5 Filter Fabric Inlet Protection @ \$50.00 Each \$250.00 62 0 Extra Bags of Cement for High-Early-Strength Concrete \$16.00 Each \$0.00 Subtotal Less Retainage \$21,631.49 Subtotal \$672,559.37 Less Amount Previously Paid \$487,174.17	54	4,000	8-Inch Non-Reinforced Concrete Pavement	@	\$27.90	Ton	\$111,600.00
57 0 Removal and Replacement of Salvaged Carriage Walk	55	0	Intentionally Left Blank	@		Ton	\$0.00
Stone Ston	56	0	4-Inch HMA Driveway	@	\$5.00	Sq. Ft.	\$0.00
Stone \$12.70 \$q. Ft. \$0.00	57	0	Removal and Replacement of Salvaged Carriage Wal	k @			
59 0 Silt Fence, Delivered, Installed and Maintained @ \$5.10 Lin. Ft. \$0.00 60 6 Straw Bales Delivered, Installed and Maintained @ \$11.00 Each \$66.00 \$60.00 61 5 Filter Fabric Inlet Protection @ \$50.00 Each \$250.00 62 Extra Bags of Cement for High-Early-Strength @ Concrete \$16.00 Each \$0.00 Subtotal Less Retainage \$694,190.86 Less Retainage \$21,631.49 Subtotal Less Amount Previously Paid \$672,559.37 487,174.17			Stone		\$12.70	Sq. Ft.	\$0.00
60 6 Straw Bales Delivered, Installed and Maintained @ \$11.00 Each \$66.00 61 5 Filter Fabric Inlet Protection @ \$50.00 Each \$250.00 62 0 Extra Bags of Cement for High-Early-Strength @ Concrete \$16.00 Each \$0.00 Subtotal Less Retainage \$21,631.49 Subtotal Less Amount Previously Paid \$672,559.37			Topsoil and Sod (Includes Stripping)		\$7.40	Sq. Yd.	\$0.00
61 5 Filter Fabric Inlet Protection @ \$50.00 Each \$250.00 62 0 Extra Bags of Cement for High-Early-Strength @ \$16.00 Each \$0.00 Subtotal \$694,190.86 Less Retainage \$21,631.49 Subtotal \$672,559.37 Less Amount Previously Paid \$487,174.17		0	Silt Fence, Delivered, Installed and Maintained		\$5.10	Lin. Ft.	\$0.00
62 Extra Bags of Cement for High-Early-Strength @ Concrete \$16.00 Each \$0.00 Subtotal \$694,190.86 Less Retainage \$21,631.49 Subtotal \$672,559.37 Less Amount Previously Paid \$487,174.17			Straw Bales Delivered, Installed and Maintained		\$11.00	Each	\$66.00
Concrete \$16.00 Each \$0.00 Subtotal \$694,190.86 Less Retainage \$21,631.49 Subtotal \$672,559.37 Less Amount Previously Paid \$487,174.17	61	5			\$50.00	Each	\$250.00
Concrete \$16.00 Each \$0.00 Subtotal \$694,190.86 Less Retainage \$21,631.49 Subtotal \$672,559.37 Less Amount Previously Paid \$487,174.17	62	0	T T T	@			
Less Retainage \$21,631.49 Subtotal \$672,559.37 Less Amount Previously Paid \$487,174.17				1	\$16.00	Each	
Subtotal \$672,559.37 Less Amount Previously Paid \$487,174.17							
Less Amount Previously Paid \$487,174.17							

This estimate has been checked by the Engineering Department and we recommend that the above amount of \$185,385.20 be allowed.

Director of Public Works

Robin/Excel/Partials/Willkomm-3857