TO THE BOARD OF PUBLIC WORKS CITY OF WAUKESHA, WISCONSIN

Periodical estimate for Partial Payment No. 4 to Reesman's Excavating and Grading, Inc., 28815 Bushnell Rd., Burlington 53105 for Genesee Street Utility and Street Improvements (Concrete Pavement).

Contract No. 3856

3/4/2014

\$1,077,134.50 (Amended \$1,122,831.50)

No	Quantity	Description	@	Cost	Per Unit	Amount
1	1,492	Lin. Ft. of 8-Inch Water Main and Fittings	@	\$89.00	Lin. Ft.	\$132,788.00
2	3	Furnish and Install 8-Inch Gate Valves	@	\$1,735.00	Each	\$5,205.00
3	4	Furnish and Install Hydrant Assembly	@	\$6,580.00	Each	\$26,320.00
4	0	Connect 3/4-Inch Copper Service Lateral (SL1)	@	\$825.00	Each	\$0.00
5	0	Connect 3/4-Inch Copper Service Lateral (SL2)	@	\$1,705.00	Each	\$0.00
6	0	Connect 1-Inch Copper Service Lateral (SL3)	@	\$965.00	Each	\$0.00
7	0	Connect 3/4-Inch Copper Service Lateral (SL4)	@	\$1,705.00	Each	\$0.00
8	0	Furnish and Install Curb Boxes and Rods Where Needed	@	\$660.00	Each	\$0.00
9	2	Abandon Existing Hydrant	@	\$566.00	Each	\$1,132.00
10	1	Abandon Valve Boxes & Manholes	@	\$1,700.00	Lump Sum	\$1,700.00
11	661	Lin. Ft. of 8-Inch PVC Sanitary Sewer	@	\$124.50	Lin. Ft.	\$82,294.50
12	16.4	Vert. Ft. of 2 – 48-Inch Diameter Sanitary Sewer Manholes	@	\$325.00	Vert. Ft.	\$5,330.00
13	0	Vert. Ft. of Chimney Replacement	@	\$675.00	Vert. Ft.	\$0.00
14	973.5	Lin. Ft. of 33 – 6-Inch Sanitary Lateral Replacement (Open Cut)	@	\$105.00	Lin. Ft.	\$102,217.50
15	494	Lin. Ft. of 6" Lateral Replacement - (Pipe Bursting)	@	\$86.50	Lin. Ft.	\$42,731.00
16	13	Excavation and Lateral Connection at Right-of-way (Pipe Bursting)	@	\$952.00	Each	\$12,376.00
17	605	Lin. Ft. of 12-Inch RCSP Storm Sewer, Class V	@	\$58.00	Lin. Ft.	\$35,090.00
18	14.75	Vert. Ft. of 3-Standard 48-Inch Diameter Storm Sewer Manholes	@	\$402.00	Vert. Ft.	\$5,929.50
19	30.1	Vert. Ft. of 7-Standard Storm Sewer Inlets	@	\$217.00	Vert. Ft.	\$6,531.70
20	1,475	Lin. Ft. of Pre-Paving Sewer Televising	@	\$1.25	Lin. Ft.	\$1,843.75
21	46	Pre-Paving Lateral Televising	@	\$217.00	Each	\$9,982.00
22	0	Cu. Yd. of Slurry Backfill	@	\$70.00	Cu. Yd.	\$0.00
23	2,900	Lin. Ft. of Concrete Curb and Gutter Removal	@	\$4.05	Lin. Ft.	\$11,745.00
24	4,400	Sq. Yd. of Pavement Removal, Reconstruction	@	\$12.00	Sq. Yd.	\$52,800.00
25	0	Lin. Ft. of Concrete Curb and Gutter Removal and Replacement	@	\$70.10	Lin. Ft.	\$0.00
26	100	Lin. Ft. of Sawcutting at Pavement Limits	@	\$6.00	Lin. Ft.	\$600.00
27	3,148	Tons of 11/4-Inch Dense Aggregate	@	\$14.50	Ton	\$45,646.00
28	1,831	Tons of 11/4-Inch Crushed Stone Backfill (Includes Undercut)	@	\$20.00	Ton	\$36,620.00
29	0	Tons of 3-Inch Crushed Stone Backfill (Includes Undercut)	@	\$21.00	Ton	\$0.00
30	915	Sq. Yd. of Geotextile Fabric, Type SAS	@	\$2.50	Sq. Yd.	\$2,287.50
31	1	Traffic Control	@	\$45,510.00	Lump Sum	\$36,408.00
32	1,560	Lin. Ft. of Shaping and Grading Roadway Base	@	\$4.50	Lin. Ft.	\$7,020.00
33	4,000	Sq. Ft. of Walk and Approach Removal	@	\$1.40	Sq. Ft.	\$5,600.00

36 1,000 Sq. Ft. of New 4-Inch Concrete Walk & Curb Ramps @ \$3.10 Sq. Ft. \$3,100.00 37 1,000 Sq. Ft. of New 6-Inch Concrete Walk & Drive Approach @ \$3.40 Sq. Ft. \$3,400.00 38 0 Sq. Ft. of New 7-Inch Concrete Walk and Drive Approach @ \$3.70 Sq. Ft. \$0.00 39 1 Lin. Ft. of New Concrete Steps @ \$35.50 Lin. Ft. \$35.50 40 0 Sq. Ft. of Detectable Warning Field @ \$35.50 Sq. Ft. \$0.00 41 2,900 Lin. Ft. of Concrete Curb and Gutter @ \$12.00 Lin. Ft. \$34,800.00 42 0 Sq. Ft. of 4-Inch HMA Driveway @ \$18.00 Sq. Ft. \$0.00 43 0 Sq. Yd. of Topsoil and Sod (Includes Stripping) @ \$7.50 Sq. Yd. \$0.00 44 0 Lin. Ft. Silt Fence, Delivered, Installed and Maintained @ \$5.00 Lin. Ft. \$0.00 45 0 Straw Bales Delivered, Installed and Maintained @ \$60.50 Each \$0.00 46 8 Filter Fabric Inlet Protection @ \$96.00 Each \$768.00 48	34	0	Lin. Ft. of Concrete Curb - Pedestrian	@	\$21.00	Lin. Ft.	\$0.00
37 1,000 Sq. Ft. of New 6-Inch Concrete Walk & Drive Approach @ \$3.40 Sq. Ft. \$3,400.00 38 0 Sq. Ft. of New 7-Inch Concrete Walk and Drive Approach @ \$3.70 Sq. Ft. \$0.00 39 1 Lin. Ft. of New Concrete Steps @ \$35.50 Lin. Ft. \$35.50 40 0 Sq. Ft. of Detectable Warning Field @ \$35.50 Sq. Ft. \$0.00 41 2,900 Lin. Ft. of Concrete Curb and Gutter @ \$12.00 Lin. Ft. \$34,800.00 42 0 Sq. Ft. of 4-Inch HMA Driveway @ \$18.00 Sq. Ft. \$0.00 43 0 Sq. Yd. of Topsoil and Sod (Includes Stripping) @ \$7.50 Sq. Yd. \$0.00 44 0 Lin. Ft. Silt Fence, Delivered, Installed and Maintained @ \$5.00 Lin. Ft. \$0.00 45 0 Straw Bales Delivered, Installed and Maintained @ \$60.50 Each \$0.00 46 8 Filter Fabric Inlet Protection @ \$96.00 Each \$768.00 47 5,024 Sq. Yds. of 8-Inch Concrete Pavement @ \$31.70 Ton \$159,260.80 48 0	35	0	Sq. Yds. of 8-Inch Concrete Pavement Patching	@	\$71.00	Sq. Yd.	\$0.00
38 0 Sq. Ft. of New 7-Inch Concrete Walk and Drive Approach @ \$3.70 Sq. Ft. \$0.00 39 1 Lin. Ft. of New Concrete Steps @ \$35.50 Lin. Ft. \$35.50 40 0 Sq. Ft. of Detectable Warning Field @ \$35.50 Sq. Ft. \$0.00 41 2,900 Lin. Ft. of Concrete Curb and Gutter @ \$12.00 Lin. Ft. \$34,800.00 42 0 Sq. Ft. of 4-Inch HMA Driveway @ \$18.00 Sq. Ft. \$0.00 43 0 Sq. Yd. of Topsoil and Sod (Includes Stripping) @ \$7.50 Sq. Yd. \$0.00 44 0 Lin. Ft. Silt Fence, Delivered, Installed and Maintained @ \$5.00 Lin. Ft. \$0.00 45 0 Straw Bales Delivered, Installed and Maintained @ \$60.50 Each \$0.00 46 8 Filter Fabric Inlet Protection @ \$96.00 Each \$768.00 47 5,024 Sq. Yds. of 8-Inch Concrete Pavement @ \$31.70 Ton \$159,260.80 48 0 Extra Bags of Cement for High-Early-Strength Concrete	36	1,000	Sq. Ft. of New 4-Inch Concrete Walk & Curb Ramps	@	\$3.10	Sq. Ft.	\$3,100.00
39 1 Lin. Ft. of New Concrete Steps @ \$35.50 Lin. Ft. \$35.50 40 0 Sq. Ft. of Detectable Warning Field @ \$35.50 Sq. Ft. \$0.00 41 2,900 Lin. Ft. of Concrete Curb and Gutter @ \$12.00 Lin. Ft. \$34,800.00 42 0 Sq. Ft. of 4-Inch HMA Driveway @ \$18.00 Sq. Ft. \$0.00 43 0 Sq. Yd. of Topsoil and Sod (Includes Stripping) @ \$7.50 Sq. Yd. \$0.00 44 0 Lin. Ft. Silt Fence, Delivered, Installed and Maintained @ \$5.00 Lin. Ft. \$0.00 45 0 Straw Bales Delivered, Installed and Maintained @ \$60.50 Each \$0.00 46 8 Filter Fabric Inlet Protection @ \$96.00 Each \$768.00 47 5,024 Sq. Yds. of 8-Inch Concrete Pavement @ \$31.70 Ton \$159,260.80 48 0 Extra Bags of Cement for High-Early-Strength Concrete @ \$12.70 Ton \$45,697.00 Extra No. 1 Contract Change Order No. 1 Subtotal \$917,258.75 \$917,258.75	37	1,000	Sq. Ft. of New 6-Inch Concrete Walk & Drive Approach	@	\$3.40	Sq. Ft.	\$3,400.00
40 0 Sq. Ft. of Detectable Warning Field @ \$35.50 Sq. Ft. \$0.00 detectable Warning Field @ \$35.50 Sq. Ft. \$0.00 detectable Warning Field @ \$12.00 Lin. Ft. \$34,800.00 detectable Warning Field @ \$12.00 Lin. Ft. \$34,800.00 detectable Warning Field @ \$18.00 Sq. Ft. \$0.00 detectable Warning Field @ \$7.50 Sq. Yd. \$0.00 detectable Warning Field @ \$5.00 Lin. Ft. \$0.00 detectable Warning Field @ \$60.50 Each \$0.00 detectable Warning Field @ \$60.50 Each \$768.00 detectable Warning Field @ \$12.70 Ton \$159,260.80 detectable Warning Field @ \$45,697.00 detectable Warning Field & \$0.00	38	0	Sq. Ft. of New 7-Inch Concrete Walk and Drive Approach	@	\$3.70	Sq. Ft.	\$0.00
41 2,900 Lin. Ft. of Concrete Curb and Gutter @ \$12.00 Lin. Ft. \$34,800.00 42 0 Sq. Ft. of 4-Inch HMA Driveway @ \$18.00 Sq. Ft. \$0.00 43 0 Sq. Yd. of Topsoil and Sod (Includes Stripping) @ \$7.50 Sq. Yd. \$0.00 44 0 Lin. Ft. Silt Fence, Delivered, Installed and Maintained @ \$5.00 Lin. Ft. \$0.00 45 0 Straw Bales Delivered, Installed and Maintained @ \$60.50 Each \$0.00 46 8 Filter Fabric Inlet Protection @ \$96.00 Each \$768.00 47 5,024 Sq. Yds. of 8-Inch Concrete Pavement @ \$31.70 Ton \$159,260.80 48 0 Extra Bags of Cement for High-Early-Strength Concrete @ \$12.70 Ton \$0.00 Extra No. 1 Contract Change Order No. I @ \$45,697.00 \$917,258.75	39	1	Lin. Ft. of New Concrete Steps	@	\$35.50	Lin. Ft.	\$35.50
42 0 Sq. Ft. of 4-Inch HMA Driveway @ \$18.00 Sq. Ft. \$0.00 43 0 Sq. Yd. of Topsoil and Sod (Includes Stripping) @ \$7.50 Sq. Yd. \$0.00 44 0 Lin. Ft. Silt Fence, Delivered, Installed and Maintained @ \$5.00 Lin. Ft. \$0.00 45 0 Straw Bales Delivered, Installed and Maintained @ \$60.50 Each \$0.00 46 8 Filter Fabric Inlet Protection @ \$96.00 Each \$768.00 47 5,024 Sq. Yds. of 8-Inch Concrete Pavement @ \$31.70 Ton \$159,260.80 48 0 Extra Bags of Cement for High-Early-Strength Concrete @ \$12.70 Ton \$0.00 Extra No. 1 Contract Change Order No. 1 @ \$45,697.00 \$917,258.75	40	0	Sq. Ft. of Detectable Warning Field	@	\$35.50	Sq. Ft.	\$0.00
43 0 Sq. Yd. of Topsoil and Sod (Includes Stripping) @ \$7.50 Sq. Yd. \$0.00 44 0 Lin. Ft. Silt Fence, Delivered, Installed and Maintained @ \$5.00 Lin. Ft. \$0.00 45 0 Straw Bales Delivered, Installed and Maintained @ \$60.50 Each \$0.00 46 8 Filter Fabric Inlet Protection @ \$96.00 Each \$768.00 47 5,024 Sq. Yds. of 8-Inch Concrete Pavement @ \$31.70 Ton \$159,260.80 48 0 Extra Bags of Cement for High-Early-Strength Concrete @ \$12.70 Ton \$0.00 Extra No. 1 Contract Change Order No. 1 @ \$45,697.00 \$917,258.75	41	2,900	Lin. Ft. of Concrete Curb and Gutter	@	\$12.00	Lin. Ft.	\$34,800.00
44 0 Lin. Ft. Silt Fence, Delivered, Installed and Maintained @ \$5.00 Lin. Ft. \$0.00 45 0 Straw Bales Delivered, Installed and Maintained @ \$60.50 Each \$0.00 46 8 Filter Fabric Inlet Protection @ \$96.00 Each \$768.00 47 5,024 Sq. Yds. of 8-Inch Concrete Pavement @ \$31.70 Ton \$159,260.80 48 0 Extra Bags of Cement for High-Early-Strength Concrete @ \$12.70 Ton \$0.00 Extra No. 1 Contract Change Order No. I @ \$45,697.00 \$45,697.00 \$917,258.75	42	0	Sq. Ft. of 4-Inch HMA Driveway	@	\$18.00	Sq. Ft.	\$0.00
45 0 Straw Bales Delivered, Installed and Maintained @ \$60.50 Each \$0.00	43	0	Sq. Yd. of Topsoil and Sod (Includes Stripping)	@	\$7.50	Sq. Yd.	\$0.00
46 8 Filter Fabric Inlet Protection @ \$96.00 Each \$768.00 47 5,024 Sq. Yds. of 8-Inch Concrete Pavement @ \$31.70 Ton \$159,260.80 48 0 Extra Bags of Cement for High-Early-Strength Concrete @ \$12.70 Ton \$0.00 Extra No. 1 Contract Change Order No. 1 @ \$45,697.00 \$45,697.00 \$917,258.75	44	0	Lin. Ft. Silt Fence, Delivered, Installed and Maintained	@	\$5.00	Lin. Ft.	\$0.00
47 5,024 Sq. Yds. of 8-Inch Concrete Pavement @ \$31.70 Ton \$159,260.80 48 0 Extra Bags of Cement for High-Early-Strength Concrete @ \$12.70 Ton \$0.00 Extra No. 1 Contract Change Order No. I @ \$45,697.00 \$45,697.00 Subtotal \$917,258.75	45	0	Straw Bales Delivered, Installed and Maintained	@	\$60.50	Each	\$0.00
48 0 Extra Bags of Cement for High-Early-Strength Concrete @ \$12.70 Ton \$0.00 Extra No. 1 Contract Change Order No. 1 @ \$45,697.00 \$45,697.00 \$917,258.75	46	8	Filter Fabric Inlet Protection	@	\$96.00	Each	\$768.00
Extra No. 1 Contract Change Order No. 1 @ \$45,697.00 \$45,697.00 \$917,258.75	47	5,024	Sq. Yds. of 8-Inch Concrete Pavement	@	\$31.70	Ton	\$159,260.80
Subtotal \$917,258.75	48	0	Extra Bags of Cement for High-Early-Strength Concrete	@	\$12.70	Ton	\$0.00
	Extra No. 1		Contract Change Order No. 1	@	\$45,697.00		\$45,697.00
Less Retainage \$28,070.79		\$917,258.75					
		\$28,070.79					
Total \$889,187.96		\$889,187.96					
Less Amount Previusly Paid \$624,160.16		\$624,160.16					
Total Amount Due \$265,027.80		\$265,027.80					

This estimate has been checked by the Engineering Department and we recommend that the above amount of \$265,027.80 be allowed.

Respectfully Submitted,

Fred V. Abadi, PhD., P.E.

FABal.

Director of Public Works

Robin/Excel/Partials/Reesman's-3856