

LANDMARKS COMMISSION APPLICATION

Monthly meeting is scheduled the first Wednesday of every month.

Application Deadline is 4:30 p.m. 12 days prior to the meeting date.

Date Received: 2-26-16	Amount Paid: 430 - Rec'd. By: Ma
app applying for a: V Certificate of Appropriateness (COA) - \$15.00 ap Landmarks Paint & Repair Grant (LCP & R) - \$15 Both - \$30.00 A. General Information:	plication fee required. .00 application fee required.
Phone-Home: 242-751.5029	Phone- Work MARKETING DIRECTOR
Mailing Address: 1233 E. BROADWAY WALL	ESHA, WI 53186 (as of 7/29/11
Chone-Work: TOMEMPEY Chone-Work: 242.441.4411	ccupation: SALES
3. Income Level Information: (Required only for the	hose applying for a LCP & R Grant)
1	ES BELOW to INDICATE WHETHER YOUR FAMILY nt for your household: 1 Family Income Level (Up to:) 1 \$58,050 1 \$62,350 1 \$66,650 1 \$70,950 2 come is Below Guidelines
istoric Property Address: 1233 E BROADWAY 1233 E BROADWAY	Construction Date/Era: 1919 Architectural Style
Brief Historic Background:	
lave there been any alterations or repairs? Yes	V No ENOT SINCE WE'VE began

If yes, describe alterations/rep	rs: PKVIOUS OWNERS MMODERED KITCHEN	
& finished 3PD Flo	AHIC GOACE.	
<u> </u>		_

D. Nature of Intended Repair(s)/Proposed Work:

Estimated start date:

Briefly and accurately describe type and location of proposed work on primary building, carriage house, outbuildings (i.e.: garage), fences (including retaining walls), paved surfaces and landscaping. Attach extra sheets and supplemental material as requested in the criteria checklist found in Section E. Be sure to reference the attached Exhibit A, which summarizes the guidelines from the Secretary of Interior's Standards for Historic Preservation Projects. Your narrative must address any of the following elements related to your project:

ROOF		CHIMNEY	
Repair or replacement?		Repair/replacement?	
Soffits/Fascia/Downspouts	secatained secatained	Flashing	
Eaves, Gutters	se attained	Tuckpointing	
Shingle type/style/color	<u> </u>		
SIDING	A	WINDOWS	
Repair or replacement?	seeaHawed	Repair/replacement?	<i>becattained</i>
Paint Colors, Materials	secattained	Materials, Other	
Shingling/Ornamentation/S	tickwork		
OTHER EXTERIOR	REPAIRS	FOUNDATION	
Awnings		Extent of repair	
Brickwork/Stonework		Tuckpointing	
Cresting		 Other	
Doors	. :		
PORCH		MISCELLANEO	US ,
Repair or replacement?	Secattained	Landscaping	Sceatacred
Front or Side, Rear	300000000000000000000000000000000000000	Fences .	
Ornamentation		Paving/Brick Pavers	
Finials, Other			
- monor	NAMES CONTROL OF THE PROPERTY		A. Article Market Control
AAAAAA F	Control of the Contro		
- WANN	teatile con-		
	o la lu		

Estimated completion date: \(\ldots \psi \psi \psi \psi \psi \psi \psi \psi
I/We intend/have already applied for the state's preservation tax credits: Yes No
Status: Application submitted
Has owner done any previous restoration/repair work on this property? V No Yes
If yes, what has been done?
Are any further repairs or alterations planned for this building for the future? \sqrt{No} Yes If yes, please describe: $NOTATNISTIME$.
E. Criteria Checklist (REQUIRED, please read carefully):
For ALL PROJECTS
 Photographs of affected areas and existing conditions from all sides Historic plans, elevations or photographs (if available) Material and design specifications, including samples and/or product brochures/literature when appropriate
For ALL NEW CONSTRUCTION/ADDITIONS/EXTERIOR ALTERATIONS/FENCING & LANDSCAPING
Site and/or elevation plan – to scale (required for all new construction or proposed additions)
For EXTERIOR PAINT WORK
Color samples (including brand of paint and product ID number) and placement on the structure
REQUIRED FOR ALL LCP & R APPLICATIONS
Provide a detailed cost estimate for these repair(s), based on the number of gallons of paint, the amount of lumber, or the number of panes of glass, etc. Be certain to separate material costs from labor. Include a written estimate(s) if available:

I have read and answered the above to the best of my knowledge, and the information I have supplied is accurate to the best of my knowledge. I agree to supply any relevant documentation that is required for the proper review of this application. If I am applying for a LCP & R, I also agree to do the intended paint and/or repair work, as outlined and proposed above, exactly as described, or I agree to return the entire amount of the grant. I understand that I, or my assistants, must finish the proposed project within one hundred twenty (120) days of the payment of the grant. Compensation for the paint/materials, acquired solely for the repairs specified above, will be paid promptly upon the receipt of the properly written billing, or in a manner to be agreed upon between the owner/renter and the landmarks Commission or its authorized representative(s). Once the proposed paint/repair project has been approved, no changes or alterations in design or color scheme are allowed without the express written approval of the Landmarks Commission or its authorized representative(s). Failure to comply with the above is sufficient cause for the grant recipient to be required to immediately repay the entire grant amount. Any and all disputes which may arise under this agreement, or its interpretation, concerning eligibility, approval, procedures or forfeitures, shall be presented in writing to the Landmarks Commission, by the applicant, within ten (10) days of the dispute. The Landmarks Commission will then make a decision, and notify the applicant of its decision in writing, within ten (10) days of receipt of the letter detailing the nature of the dispute. These decisions will be final and bipding.

be final and binding. Signed: MUMANNEW	Date: 7/20/2010
Office use only: Received by:	Inspected/Photographed By
COA Approved: Yes No	Authorized By
Moved:	
Seconded:	
Vate:	
Comments:	
LCP & R Approved: Yes No	Authorized By
Moved:	
Seconded:	
Vote:	
Comments:	
A Li Maria -	

1233 E Broadway Proposed Projects

Owners: Tom & Angie Emrey
July 26, 2016

Roof: Repair/Correction

penetration issues and has undermined and damaged the plaster in the area. It appears the picture on left below). previous owners attempted to address the matter, but it has not been properly corrected (see Currently there is a building projection on the east elevation with has a flat roof that has water

on right below). addresses the diversion of water. We request your consideration to be allowed to apply the same roof structure design solution to the east elevation that is now at the south elevation (see picture There is another building projection on the south elevation and has a roof structure that properly







Additional Pictures









Soffits/Fascia

snow has been mostly corrected, but the previous damaged wood due to the rain and snow (see pictures at right). Apparently with the placement of new gutters and downspouts the diversion of rain and trim pieces pieces now need to be replaced. We request your consideration to There are many fascia and soffit wood trim pieces that have rotten remove and replace the wood trim pieces with similar profile wood





	·		

Downspouts


downspouts and the water has damaged the plaster along the base of the stairs/stoop and building. This is also a concern with water seeping The front elevation has a gable roof over the door and an "eyebrow" roof above the windows. Currently there are no gutters and downspouts to be installed at this location. into the basement. Similar conditions exist at the west sunroom roof line. We request your consideration to allow for gutters and





Siding

selection have yet to be determined. (see pics). with a top coat, but to properly correct the undermined/damage plaster, it would need damaged the existing plaster. It appears there have been attempts to repair the plaster replacement of the undermined/damage plaster and the painting of the building, color paint to cover the new plastered areas. We request your consideration to allow for the to be cut out and replaced. With the plaster replaced the building would need to be Due to the improper fix to the east building projection water has undermined and





	·	

Porch

stairs have uneven heaving and settling and has cause a safety hazard at the step. The stoop and stair will need to be mudjacked to achieve proper grade and placement. Once that is done the plaster at the stairs around this area will need to be replaced. We request your Due to the roof rain run- off and improper drainage, the stoop and replacement of the damage plaster consideration to all for the correction to the stoop and stairs and the





Windows

all have the consistent look. windows are missing and/or in disrepair and need to be Many of the existing combination screen and storm replace all the combination screens and storm so they are placed and replaced. We request your consideration to







Garage

or removal of the existing one stall garage standard size car be would not allow for the storage of lawn tracker, snowblower, two stall garage is needed. The garage has structural issues. The previous owner outdoor grille and other yard equipment. We request your consideration for the razing merely as storage shed and not a practical size garage. It may accommodate one possibly a new roof. Even if these repairs were made the garage size is obsolete and is pushed the south and east wall off the foundation when parking the car in the garage The existing structure in its current condition is unusable as a single stall garage and plaster, rotted framing and sheathing, and it is in need of a new garage door and resulting in foundation wall and plaster damage. Additionally there is deteriorating





	·	

Additional Garage Pictures



Additional Garage Pictures







\$34,900.00	\$8,150.00	\$26,750.00	Total Costs		
\$15,000.00	\$0.00	\$15,000.00	Raze the existing garag structure, footing, foundation and slab \$15,000. Build an architecturally compatible garage structure at a later date (cost unknown at this date.	Raze exiting garage structure due the many defects (south and east wall off the foundation and the foundation has severe cracks, deteriorating plaster, rotten fazcia soffit and walls) and obsolete garage design, size not able to accommdate current garage storag needs	Garage
\$8,600.00	\$4,800.00	\$3,800.00	Combination screens and storms, glass	Replace broken glass panes and remove and replace combination sreens and storms	Windows
\$1,000.00	\$0.00	\$1,000.00	Mudjacking service	Mudjack stoop to maintain proper pitch away from the building, mudjack stairs to match stoop elevation	Porch Stoop/Stairs
\$5,200.00	\$1,700.00	\$3,500.00	Plaster, paint	Remove and replace damaged plaster at the east elevation, the stoop area and along the north elevation at grade	Siding
\$800.00	\$300.00	\$500.00	Gutters and downspouts	Add gutters and downspouts at the north elevation at roof entry and and "eyebrow" over the window and at lower sunroom roof elements	Downspouts
\$3,000.00	\$900.00	\$2,100.00	Wood trim pieces, paint and some plaster repair	Remove and replace rotted wood trim pieces at the soffits and fascia and window trim pieces	Soffit & Fascia
\$1,300.00	\$450.00	\$850.00	Wood framing, shingle so match existing, paint to match existing	Provide roof structure at East building projection to be similar with South building projection	Roof Structure
Total Cost	Materials Cost	Labor Cost		Repair Plan	Issue
TOWN THE TAX TO THE TA			Repair Plan - 1233 E Broadway	Rep	