



## Legislation Text

---

**File #:** ID#17-1070, **Version:** 3

---

Upon review of the previous item (ID#17-1069), a discrepancy in the parking zone was discovered on the northeast side of Madison Street resulting in a gap in restricted parking. For safety reasons, parking should not be allowed on the northeast side of Madison Street from Randall Street to Spring Street. This item, if approved, will resolve the discrepancy and fully install No Parking Any Time on the northeast side of Madison Street from Randall to Spring.