## July 20, 2017

## TO THE BOARD OF PUBLIC WORKS CITY OF WAUKESHA, WISCONSIN

Periodical estimate for Partial Payment No. 1 to PTS Contractors, Inc., 4075 Eaton Road, Green Bay, WI 54311 for Jefferson Avenue, Oscar Street, Greenway Terrace And Butler Drive Utility Improvements.

Contract No. 3998 4/18/2017 \$ 1,100,086.75

Item No	Bid Quantity	Completed Quantity	Description		Cost	Per Unit	Amount
1	4	0	Lower 1" Service Lateral (SL1)	@	\$ 4,212.00	Each	\$0.00
2	3	0	Insulate 1" Copper Service Lateral (SL2)	@	\$ 706.00	Each	\$0.00
3	100	0	Additional Insulation of 1" Copper Service	@	\$ 5.40	Lin. Ft.	\$0.00
4	14	0	Furnish and Install Curb Boxes & Rods (If needed)	@	\$ 107.00	Each	\$0.00
5	14	0	Furnish and Install Curb Stop (If needed)	@	\$ 209.00	Each	\$0.00
6	580	576.5	Lin. Ft. of 21-Inch PVC Sanitary Sewer	a	\$ 150.00	Lin. Ft.	\$86,475.00
7	2,329	42	Lin. Ft. of 18-Inch PVC Sanitary Sewer	<u>@</u>	\$ 132.00	Lin. Ft.	\$5,544.00
8	17	0	Lin. Ft. of 8-Inch PVC Sanitary Sewer	a	\$ 266.00	Lin. Ft.	\$0.00
9	180	0	Lin. Ft. of 6-Inch PVC Sanitary Lateral	@	\$ 182.00	Lin. Ft.	\$0.00
9A	7	6	21-Inch x 21-Inch x 6-Inch PVC Sanitary	<b>@</b>	\$ 1,410.00	Each	\$8,460.00
			Lateral Wye Connection (SDR 35)				
9B	14	0	18-Inch x 18-Inch x 6-Inch PVC Sanitary Lateral Wye Connection (SDR 26)	@	1,190.00	Each	\$0.00
9C	15	0	18-Inch x 18-Inch x 6-Inch PVC Sanitary Lateral Wye Connection (SDR 35)	@	1,067.00	Each	\$0.00
10	70	0	Vert. Ft. 6-Inch PVC Sanitary Lateral Riser	@	\$ 68.00	Vert. Ft.	\$0.00
11	135	20	Vert. Ft. of 48-Inch Diameter Sanitary	<b>@</b>	\$ 234.00	Vert. Ft.	\$4,680.00
			Manhole				
12	13	0	Vert. Ft. of 48-Inch Diameter Sanitary Sewer Manhole with Outside Drop	@	\$ 355.00	Vert, Ft.	\$0.00
13	90	0	12-Inch PVC Sanitary Force Main	@	\$ 115.00	Lin. Ft.	\$0.00
14	1	0	Abandon Existing Force Main	@	\$ 580.00	Lump Sum	\$0.00
15	1	0	Remove Existing Inside Pipe Drop	@	\$ 463.00	Lump Sum	\$0.00
16	1,294	0	Lin. Ft. of 15-Inch Sanitary Sewer Lining (CIPP)	@	\$ 40.00	Lin, Ft.	\$0.00
17	15	0	Sanitary Lateral Reinstatement	@	\$ 153.00	Each	\$0.00
18	15	0	Sanitary Lateral Connection Test and Seal	@	\$ 260.00	Each	\$0.00
19	10	0	Rehabilitate Sanitary Manhole with Cementitious Liner (Approx. 110 Vert. Ft.)	@	\$ 1,250.00	Each	\$0.00
20	4	0	Sanitary Manhole Bench / Invert / Trough	@	\$ 521.00	Each	\$0.00
21	1	0	Sanitary Manhole Bench / Invert / Trough	@	\$ 695.00	Each	\$0.00
22	7	0	Sanitary Manhole Chimney Seal	@	\$ 317.00	Each	\$0.00
23	12	0	Chimney Replacement	@	\$ 673.00	Each	\$0.00
24	50	0	Storm Sewer Inlet Repair	@	\$ 333.00	Vert. Ft.	\$0.00
25	10	0	Storm Sewer Manhole Repair	@	\$ 333.00	Vert. Ft.	\$0.00
26	4,350	0	Lin. Ft. of Sanitary Sewer Televising -	@	\$ 1.10	Lin. Ft.	\$0.00

27	1,220	0	Lin. Ft. of Storm Sewer Televising - Prepaving	$\alpha$	\$	1.10	Lin. Ft.	\$0.00
28	37	0	Sanitary Lateral Televising - Prepaying	@	\$	290.00	Each	\$0.00
29	80	0	Cu. Yds. of Slurry Backfill	@	\$	68.00	Cu. Yd.	\$0.00
30	15,900	0	Sq. Yds. of Pavement Removal	@	\$	1.20	Sq. Yd.	\$0.00
31	650	0	Lin. Ft. of Sawcutting at Payement Limits	@	\$	1.80	Lin. Ft.	\$0.00
32	1,950	0	Tons of 11/4-Inch Dense Aggregate	@	\$	12.20	Tons	\$0.00
33	100	0	Tons of 11/4-Inch Crushed Stone Backfill	@	\$	20.00	Tons	\$0.00
34	100	0	Tons of 3-Inch Crushed Stone Backfill	@	\$	21.00	Tons	\$0.00
35	100	0	Sq. Yds. of Geotextile Fabric, Type SAS	@	\$	2.00	Sq. Yd.	\$0.00
36	1	0.25	Traffic Control	æ	\$	7,165.00	Lump Sum	\$1,791.25
37	5,650	0	Sq. Ft. of Walk and Drive Approach Removal	@	\$	0.95	Sq. Ft.	\$0.00
38	1,200	0	Lin. Ft. of Concrete Curb and Gutter Removal	@	\$	30.00	Lin. Ft.	\$0.00
39	5,300	0	Sq. Ft. of New 4-Inch Concrete Walk and Curb	@	\$	5.20	Sq. Ft.	\$0.00
40	350	0	Sq. Ft. of New 6-Inch Concrete Walk and	@	\$	5.60	Sq. Ft.	\$0.00
41	368	0	Sq. Ft. of Detectable Warning Surface	@	\$	28.50	Sq. Ft.	\$0.00
42	50	0	Lin. Ft. of Concrete Curb - Pedestrian	a	\$	29.50	Lin. Ft.	\$0.00
43	3,000	0	Tons of HMA Pavement Type 3 LT 58-28 H	@	\$	54.60	Tons	\$0.00
44	2,000	0	Tons of HMA Pavement Type 5 LT 58-28 H	<u>a</u>	\$	50.95	Tons	\$0.00
45	100	0	Sq. Ft. of 4-Inch HMA Pavement	@	\$	20.10	Sq. Ft.	\$0.00
46	375	0	Lin. Ft. of Pavement Markings, Yellow,	@	\$	2.65	Lin. Ft.	\$0.00
			Epoxy, 4-Inch	_				
47	1,075	0	Lin. Ft. of Pavement Markings, White, Epoxy, 6-Inch	@	\$	4.70	Lin. Ft.	\$0.00
48	250	0	Lin. Ft. of Pavement Markings, White, Epoxy, 18-Inch	@	\$	5.80	Lin. Ft.	\$0.00
49	1,100	0	Topsoil and Sod (Includes Stripping)	@	\$	7.10	Sq. Yd.	\$0.00
50	20	0	Silt Fence, Delivered, Installed and Maintained		\$	5.10	Lin, Ft,	\$0.00
51	20	0	Straw Bales Delivered, Installed and	<u>a</u>	\$	15.30	Each	\$0.00
			Maintained					
52	38	15	Filter Fabric Inlet Protection	<b>@</b>	\$	46.00	Each	\$690.00
53	20	0	Extra Bags of Cement for High-Early-Strength Concrete	@	\$	11.00	Each	\$0.00
	Total  Less Retainage							\$107,640.25
								\$5,382.01
Total								\$102,258.24
			Less Previosuly Paid					\$0.00
			Total Amount Due				-	\$102,258.24
			Total Almount Duc					Ψεθωμοθιώτ

This estimate has been checked by the Engineering Department and we recommend that the above amount of \$102,258.24 be allowed.

Respectfully Submitted,

Fred V. Abadi, PhD., P.E. Director of Public Works