



## **CERTIFICATE OF APPROPRIATENESS APPLICATION**

Date Received:
The Landmarks Commission meets on the first Wednesday of every month. Applications are due TWO
WEEKS before the meeting date. Any application received after that date may be placed on the agenda for
the following month.
Before submitting your application you should discuss your plans with City staff and/or read and understand the Landmarks Commission Design Policies.
Staff contact info - Phone: 262-524-3529, Email: cgriffith@waukesha-wi.gov
PLEASE READ AND SIGN: The information in this application is accurate to the best of my knowledge. I agree to supply any relevant documentation that is required for the proper review of this application, and I understand that any missing or incomplete information may delay the review process. By signing this I also authorize the City of Waukesha or its agents to enter upon my property for the purpose of reviewing this application.  Signed:  Date: 04/30/3025  Address of Property: 305 MCCALL ST WAUKESHA, WI 53/86
Address of Property: 303 MICCALL ST WAUKESIAA, WI 33186
Applicant Name: <u>CAROZYN COATES</u>
Phone: (715) 212-8396
Email: <u>Carolyn coat @ gmail.com</u> Mailing Address: <u>305 MCCqu ST WAUKES HA, WI 53186</u>
Mailing Address: \( \frac{1}{305} \textit{McCaucst} \text{WAUKESHA, wt 53/86} \)
\$15.00 Fee: 4/5 ck#1029
Brief History of the property if known: Victorian Single family home constructed

in 1895. I have owned this property for 5 years.





## Please describe your proposed work in as much detail as possible below.

If you need additional space, feel free to submit a separate written explanation. Before submitting the application, you should contact Community Development staff to discuss your project. You should also familiarize yourself with the Landmarks Commission Design Guidelines

Repair of chimney leak, Additional repairs needed to secure loose roof shingles for application of Cericade on house.
loose roof shingles for application of Cericade on house.
There is an orea of the roof that is leaking into the attice (pictures enclosed). This leaking has caused damage to I'm floor
(pictures enclosed). This leaking has caused damage to I'm floor
- Ent Cerlinge
There is an area around the Chimney flashing that is allowing water to get into affic also (picture enclosed)
Cericade is a roof system that is designed to fortify existing
roof system. Existing shingles will not be replaced, but cleaned and secured as needed prior to Cericade application.
- The to the total of the total
Total Estimated cost of the project: # //, 9/9. & 7
☐ I plan to apply/ ☐ I have already applied for State/Federal Historic Preservation Tax Credits
I would like to apply for a Paint and Repair Grant (include a Paint and Repair Grant application with this form).
☐ I would like information about City grants and loans for commercial properties.

The following additional submittal items are always helpful and may be required depending on the project:

- An estimate or contract from a building professional with details of the project.
- Photos of impacted areas.
- Elevation drawings and/or site plans.
- Material or color samples.