

Office of the Clerk Treasurer

201 Delafield Street
Waukesha, Wisconsin 53188-3633

Gina Kozlik, Clerk Treasurer

clerktreas@waukesha-wi.gov
1-262-524-3550

February 15, 2023

To: Natalie Driebel, Accounting Clerk, Finance Department

Re: Claim for Property Damage


**Submitted by: Borgelt, Powell, Peterson & Frauen S.C.
1243 North 10th Street, Suite 300
Milwaukee, WI 53205**

**On Behalf of: West Bend Mutual Insurance Company
West Bend Insured: Office Pro, INC**

Date Claim Received: February 15, 2023

The enclosed is being sent to you to provide to our insurance or as needed for your review.

Sincerely,




**Gina Kozlik
City of Waukesha Clerk-Treasurer**

Cc: Clerk (original) / Finance / Attorney / Park, Recreation, and Forestry

B
BORGELT POWELL
PETERSON & FRAUEN S.C.

Attorneys and Counselors
Established 1881

Patrick D. McNally
Direct Dial: 414-287-9156
Email: pmcnally@borgelt.com
Website: www.borgelt.com



1243 North 10th Street, Suite 300
Milwaukee, WI 53205
(414) 276-3600
(414) 276-0172 (fax)

February 14, 2023

Via Process Server

Ms. Gina Kozlik
Clerk/Treasurer
City of Waukesha
201 Delafield Street
Waukesha, WI 53188

AGENT FOR STATE PROCESS SERVERS, INC.

Time of Service 1230 am/pm C

Date of Service Served upon 2/15/23

at C

Personal Service Substitute personal service
 Deposition Service Posting

Re: *West Bend Mutual Insurance Company's Notice of Injury and Claim Pursuant to Wis. Stat. Sec. 893.80*

Our Client:	West Bend Mutual Insurance Company
West Bend Insured:	Office Pro, Inc.
West Bend Claim No.:	AP85223
Date of Loss:	October 20, 2022
Location:	Approx. 2300 Block of Springdale Road (southbound lane) Waukesha, Wisconsin

Dear Madam Clerk:

This letter will serve as Wis. Stat. Sec. 893.80 notice of injury and claim submitted by the undersigned's office on behalf of West Bend Mutual Insurance Company to and against the City of Waukesha relating to the property damage incident that occurred on or near the tree lawn (green space between curb and sidewalk) on the west side of Springdale Road between Hollidale Drive to the north and Rambling Rose Road to the south in Waukesha, Wisconsin on October 20, 2022 at approximately 4:00 p.m. central standard time. At that time and place, a low hanging branch or branches of a tree on the tree lawn on the west side of Springdale Road caused significant property damage to the vehicle owned by Office Pro, Inc. being driven southbound on Springdale Road.

BORGELT POWELL
PETERSON & FRAUEN, S.C.

Ms. Gina Kozlik – City of Waukesha, Clerk/Treasurer

Re: *West Bend Mutual's Notice of Injury and Claim Pursuant to Wis. Stat. Sec. 893.80*

West Bend Claim No. AP85223

February 14, 2023

Page | 2

The Office Pro, Inc. vehicle was a white 2017 Ford F650 XLT 4x2 chassis and cab with chassis mounted bed [VIN: 1FDNF6DC7HDB10880; WI license plate number: 83170].

As the insurer of Office Pro, Inc., West Bend Mutual made first-party property damage claim payments pursuant to its insurance contract provisions (auto policy number A893951) totaling \$21,945.56 for the collision repair work. Office Pro, Inc. had a \$500.00 deductible applied to its first-party claim. The combined total of West Bend Mutual's subrogation interest (including deductible to be reimbursed to the insured) is \$22,445.56.

Enclosed with this letter notice please find documents and things Bates-stamped as *WBM_Office Pro_00001* through *WBM_Office Pro_00062* in support of West Bend Mutual's subrogation interest. Specifically, payment screens for the \$21,945.56 payments made by West Bend Mutual are Bates-stamped as *WBM_Office Pro_00001 - 00002*, photos of the damage to the Office Pro truck are Bates-stamped as *WBM_Office Pro_00003 - 00032, 00036 - 00052, and 00060 - 00061*, and repair appraisal, estimate, bill, and related correspondence are Bates-stamped as *WBM_Office Pro_00033 - 00035, 00053 - 00059, and 00062*.

Based on West Bend Mutual investigation to date, this property damage incident was caused by the failure of the City of Waukesha to properly, reasonably, and safely trim the trees located on the tree lawn on the above-identified stretch of the west side of Springdale Road. Additionally, West Bend Mutual believes that the City of Waukesha created and maintained a public nuisance by allowing said tree limbs to project over Springdale Road, a public street, causing contact with the Office Pro truck being lawfully operated on Springdale Road. Upon information and belief, the City of Waukesha's creation and maintenance of that public nuisance was in violation of City of Waukesha Municipal Code Sec. 12.05, "Public Nuisances Affecting Peace and Safety Defined".

The City of Waukesha received actual notice of this claim, per Wis. Stat. Sec. 893.80(1d)(a), by letter, dated November 30, 2022, from Ash Gadke, Sr. Subrogation Representative with West Bend Mutual, addressed to the City of Waukesha – Office of the Clerk/Treasurer.

Payment in the amount **\$22,445.56** (West Bend Mutual's subrogation interest plus deductible) should be made by check to "Borgelt, Powell, Peterson & Frauen, S.C. Client Trust Account" [Tax I.D. #39-1233261] and mailed to my attention at our Milwaukee location.

BORGELT POWELL
PETERSON & FRAUEN, S.C.

Ms. Gina Kozlik – City of Waukesha, Clerk/Treasurer

Re: *West Bend Mutual's Notice of Injury and Claim Pursuant to Wis. Stat. Sec. 893.80*

West Bend Claim No. AP85223

February 14, 2023

Page | 3

Very truly yours,

BORGELT, POWELL, PETERSON & FRAUEN, S.C.



Patrick D. McNally

PDM/mf
enc.

CLAIM NUMBER

AP85223

LOSS DESCRIPTION

IV IN/NEAR WAUKESHA AND PART OF A TREE PUNCTURED THE SIDE OF THE TRUCK. SAID TREE WAS HANGING OVER INTO THE LANE OF TRAFFIC.

LOSS ITEM DETAIL

CLAIMANT NAME:	OFFICE PRO, INC	RESERVE TYPE:	LOSS
UNIT DESCRIPTION:	2017 FORD F650 XLT 4X2 CHASSIS & CAB REGULAR CAB SUPER DUTY W/AIR BRAKES 1FDNF6DC7HDB10880	MAJOR PERIL:	AUTO PHYSICAL DAMAGE - COLLISION
		CAUSE OF LOSS:	AUTO PHYSICAL DAMAGE -COLLISION
		RESERVE CATEGORY:	GENERAL

TRANSACTION DATE	TRANSACTION TYPE	PAYEE(S)	DRAFT NUMBER	AMOUNT
11/21/2022	FINAL PAYMENT	MORGAN CORPORATION	CK16908561	\$21,945.56
TOTAL PAYMENTS:				\$21,945.56

[Make Payment](#)
[Onset Payment](#)
[Printer Friendly](#)
[Claim Detail](#)
[Return to Summary](#)

CLAIM NUMBER

APB5223

LOSS DESCRIPTION

IV IN/NEAR WAUKESHA AND PART OF A TREE PUNCTURED THE SIDE OF THE TRUCK. SAID TREE WAS HANGING OVER INTO THE LANE OF TRAFFIC.

LOSS ITEM DETAIL

CLAIMANT NAME: OFFICE PRO, INC	RESERVE TYPE: LOSS
UNIT DESCRIPTION: 2017 GMC/CHEVY 4X2 LOW CAB FORWARD 4500XD 71" BBC CAB & CHASSIS 176" WHEELBASE JALCDW168H7003088	MAJOR PERIL: AUTO PHYSICAL DAMAGE - COLLISION
	CAUSE OF LOSS: AUTO PHYSICAL DAMAGE - COLLISION
	RESERVE CATEGORY: GENERAL

PAYMENT DETAIL

CHECK NUMBER: VP14092139	CHECK STATUS: DISBURSED
PAYMENT AMOUNT: 521,945.56	ISSUED DATE: 11/8/2022
PAYMENT MADE DATE: 11/8/2022 4:25:55 PM	PAYMENT MADE BY: JAMES BANGEN
PAYMENT SYSTEM: ClaimsPay	PAID DATE:
PAYMENT METHOD: Virtual Payment	PAYMENT METHOD LAST 4: 0061
INVOICE NUMBER: 0	SPECIAL PROCESSING: NONE

[View Payment Detail History](#)

PAYEE INFORMATION

PAYEE NAME

MORGAN CORPORATION

PAY TO THE ORDER OF (AS PRINTED ON CHECK)

MEMO PHRASE

COVERAGE : COLLISION - 2017 CHEVY 4500XD JALCDW168H7003088 REPAIRS LESS THE \$500 DEDUCTIBLE

MAIL TO INFO

MORGAN CORPORATION
23792 NETWORK PLACE
CHICAGO , IL 60673-1237

PAYMENT BREAKDOWN

MAJOR PERIL:	AUTO PHYSICAL DAMAGE - COLLISION
CAUSE OF LOSS:	AUTO PHYSICAL DAMAGE - COLLISION -
RESERVE CATEGORY:	GENERAL
CATEGORY:	
AMOUNT:	\$21,945.56
TRANSACTION CATEGORY:	

InsurPay Contact Information

Email support@insurpay.com
Phone 1-855-682-1762

Thanks,



Claim Reference Id : AP85223-1
File Name : IMG_2153.JPG
File Date : 11/01/2022
Label :
Note :
Photo Location :
Photo Taken By :
Estimate Indicator : E01



Claim Reference Id : AP85223-1
File Name : IMG_2170.JPG
File Date : 11/01/2022
Label :
Note :
Photo Location :
Photo Taken By :
Estimate Indicator : E01



Claim Reference Id : AP85223-1
File Name : IMG_2169.JPG
File Date : 11/01/2022
Label :
Note :
Photo Location :
Photo Taken By :
Estimate Indicator : E01



Claim Reference Id : AP85223-1
File Name : IMG_2159.JPG
File Date : 11/01/2022
Label :
Note :
Photo Location :
Photo Taken By :
Estimate Indicator : E01



Claim Reference Id : AP85223-1
File Name : IMG_2167.JPG
File Date : 11/01/2022
Label :
Note :
Photo Location :
Photo Taken By :
Estimate Indicator : E01



Claim Reference Id : AP85223-1
File Name : IMG_2155.JPG
File Date : 11/01/2022
Label :
Note :
Photo Location :
Photo Taken By :
Estimate Indicator : E01



Claim Reference Id : AP85223-1
File Name : IMG_2171.JPG
File Date : 11/01/2022
Label :
Note :
Photo Location :
Photo Taken By :
Estimate Indicator : E01



Claim Reference Id : AP85223-1
File Name : IMG_2150.JPG
File Date : 11/01/2022
Label :
Note :
Photo Location :
Photo Taken By :
Estimate Indicator : E01



Claim Reference Id : AP85223-1
File Name : IMG_2162.JPG
File Date : 11/01/2022
Label :
Note :
Photo Location :
Photo Taken By :
Estimate Indicator : E01



Claim Reference Id : AP85223-1
File Name : IMG_2179.JPG
File Date : 11/01/2022
Label :
Note :
Photo Location :
Photo Taken By :
Estimate Indicator : E01



Claim Reference Id : AP85223-1
File Name : IMG_2154.JPG
File Date : 11/01/2022
Label :
Note :
Photo Location :
Photo Taken By :
Estimate Indicator : E01



Claim Reference Id : AP85223-1
File Name : IMG_2163.JPG
File Date : 11/01/2022
Label :
Note :
Photo Location :
Photo Taken By :
Estimate Indicator : E01



Claim Reference Id : AP85223-1
File Name : IMG_2158.JPG
File Date : 11/01/2022
Label :
Note :
Photo Location :
Photo Taken By :
Estimate Indicator : E01



Claim Reference Id : AP85223-1
File Name : IMG_2152.JPG
File Date : 11/01/2022
Label :
Note :
Photo Location :
Photo Taken By :
Estimate Indicator : E01



Claim Reference Id : AP85223-1
File Name : IMG_2165.JPG
File Date : 11/01/2022
Label :
Note :
Photo Location :
Photo Taken By :
Estimate Indicator : E01



Claim Reference Id : AP85223-1
File Name : IMG_2174.JPG
File Date : 11/01/2022
Label :
Note :
Photo Location :
Photo Taken By :
Estimate Indicator : E01



Claim Reference Id : AP85223-1
File Name : IMG_2149.JPG
File Date : 11/01/2022
Label :
Note :
Photo Location :
Photo Taken By :
Estimate Indicator : E01



Claim Reference Id : AP85223-1
File Name : IMG_2161.JPG
File Date : 11/01/2022
Label :
Note :
Photo Location :
Photo Taken By :
Estimate Indicator : E01



Claim Reference Id : AP85223-1
File Name : IMG_2173.JPG
File Date : 11/01/2022
Label :
Note :
Photo Location :
Photo Taken By :
Estimate Indicator : E01



Claim Reference Id : AP85223-1
File Name : IMG_2164.JPG
File Date : 11/01/2022
Label :
Note :
Photo Location :
Photo Taken By :
Estimate Indicator : E01



Claim Reference Id : AP85223-1
File Name : IMG_2147.JPG
File Date : 11/01/2022
Label :
Note :
Photo Location :
Photo Taken By :
Estimate Indicator : E01



Claim Reference Id : AP85223-1
File Name : IMG_2157.JPG
File Date : 11/01/2022
Label :
Note :
Photo Location :
Photo Taken By :
Estimate Indicator : E01



Claim Reference Id : AP85223-1
File Name : IMG_2148.JPG
File Date : 11/01/2022
Label :
Note :
Photo Location :
Photo Taken By :
Estimate Indicator : E01



Claim Reference Id : AP85223-1
File Name : IMG_2156.JPG
File Date : 11/01/2022
Label :
Note :
Photo Location :
Photo Taken By :
Estimate Indicator : E01



Claim Reference Id : AP85223-1
File Name : IMG_2166.JPG
File Date : 11/01/2022
Label :
Note :
Photo Location :
Photo Taken By :
Estimate Indicator : E01



Claim Reference Id : AP85223-1
File Name : IMG_2151.JPG
File Date : 11/01/2022
Label :
Note :
Photo Location :
Photo Taken By :
Estimate Indicator : E01



Claim Reference Id : AP85223-1
File Name : IMG_2168.JPG
File Date : 11/01/2022
Label :
Note :
Photo Location :
Photo Taken By :
Estimate Indicator : E01



Claim Reference Id : AP85223-1
File Name : IMG_2160.JPG
File Date : 11/01/2022
Label :
Note :
Photo Location :
Photo Taken By :
Estimate Indicator : E01



Claim Reference Id : AP85223-1
File Name : IMG_2178.JPG
File Date : 11/01/2022
Label :
Note :
Photo Location :
Photo Taken By :
Estimate Indicator : E01



Claim Reference Id : AP85223-1
File Name : IMG_2172.JPG
File Date : 11/01/2022
Label :
Note :
Photo Location :
Photo Taken By :
Estimate Indicator : E01

RAC Adjustments, Inc.
1740 S. Bell School Rd. Suite A, Cherry Valley, IL 61016
(414) 242-0406
Fax: (815) 349-1000
Email: btate@racadj.com

APPRAISAL REPORT

DAMAGE ASSESSED BY: Brent Tate

FILE NUMBER: 607519
CLAIM NUMBER: AP85223-1
DATE OF LOSS: 10/20/2022
TYPE OF LOSS: Collision
APPRAISED FOR: James Bangen

ASSIGNMENT DATE: None
CONTACT DATE: None
INSPECTION DATE: 10/27/2022
REC'D DATE: None

Point(s) of Impact

1 Right Front Corner (P)

INSURED: Office Pro
1810 SUTLER AVE
BELOIT, WI 53511

(608) 531-6001 ext. 208

CLAIMANT: None

OWNER: Office Pro
1810 SUTLER AVE
BELOIT, WI 53511

(608) 531-6001 ext. 208

BODY SHOP: Morgan Truck Body
3100 E Morgan Way |
Janesville, WI 53546
(800) 477-2244 ext. 4225

(608) 295-2826

25-1151457

INSPECTION SITE: Office Pro
1810 Sutler Ave
Beloit, WI 53511

QUALITY RECYCLED PARTS: No
AFTERMARKET NEW PARTS: Yes
VEHICLE DRIVEABLE: Yes

Comments:

VEHICLE IS REPAIRABLE

Inspected vehicle at Office Pro in Beloit, WI on 10/27/2022. Insured was on vacation the day of inspection and was unable to unlock the vehicle for me to obtain mileage. I was able to obtain parts price from manufacturer and reached an agreed price with insured's shop of choice. Explained the repair process to shop and insured and released a copy of the estimate to both. Per adjuster, no betterment on the decals.

COMPARISON ESTIMATE: 0.00
APPRAISER ESTIMATE: 21,945.56
AGREED UPON AMOUNT: 0.00

TOWING: 0.00
STORAGE: 0.00
DEDUCTIBLE: 500.00

ACTUAL CASH VALUE: 0.00
SALVAGE VALUE: 0.00
SETTLEMENT: 0.00
REPAIR VS. ACV: 0.00

DRAFT/CHECK NUMBER: 0
DRAFT/CHECK AMOUNT: 0.00
DATE ISSUED: None

ESTIMATE FEE: 0.00
TRAVEL EXPENSE: 0.00
PHOTO EXPENSE: 0.00
MISC EXPENSE: 0.00
TOTAL CHARGES: 0.00



RAC Adjustments, Inc.
1740 S Bell School Road
Suite A
Cherry Valley, IL 61016
Phone: 815-968-7686
Toll Free: 877-240-0180
Fax: 815-633-5086
Tax ID #: 36-3694468

FINAL

West Bend Mutual Insurance
Company
1900 South 18th Avenue
West Bend, WI 53095
ATTENTION: Bangen, James

INVOICE #: RAC - 607519-1
INVOICE DATE: 11/1/2022
INVOICE DUE DATE: 12/1/2022

CLAIM INFORMATION

INSURED: OFFICE PRO INC
INSURED POLICY #:
OUR FILE #: RAC - 607519
YOUR FILE #: AP85223-1

ADJUSTER: Tate, Brent
LOSS DATE: 10/20/2022
LOSS UNIT: Auto Appraisal

BILLABLE ITEMS

ITEM	DESCRIPTION	QTY	RATE	PRICE
Auto Fee Schedule	Auto Appraisal Per Fee Schedule	1	\$540.00	\$540.00
Auto Mileage		42.6	\$1.00	\$42.60
Auto Photo		8	\$1.00	\$8.00
Auto Telephone		0	\$1.00	\$0.00
Auto Clerical Admin	Auto Clerical	15	\$1.00	\$15.00
EXPENSES				\$0.00
SUBTOTAL:				\$605.60
TAX & FEES:				\$0.00
TOTAL:				\$605.60

RAC Adjustments, Inc. Auto Photo Sheet



VIN



ID Tag

RAC Adjustments, Inc. Auto Photo Sheet



Liftgate



Liftgate ID

RAC Adjustments, Inc. Auto Photo Sheet



rear



Right rear

RAC Adjustments, Inc. Auto Photo Sheet



Left rear



Left front

RAC Adjustments, Inc. Auto Photo Sheet



Right front



Right side

RAC Adjustments, Inc. Auto Photo Sheet



Radius panel



Side

RAC Adjustments, Inc. Auto Photo Sheet



side



Side

RAC Adjustments, Inc. Auto Photo Sheet



Side post



Right rear damage

RAC Adjustments, Inc. Auto Photo Sheet



Door frame



Interior

RAC Adjustments, Inc. Auto Photo Sheet



Unrelated prior damage



Water stains

RAC Adjustments, Inc. Auto Photo Sheet



Water stains




roof

RAC Adjustments, Inc. Auto Photo Sheet



Left inner wall



Left inner brace

RAC Adjustments, Inc. Auto Photo Sheet



roof



Interior

RAC Adjustments, Inc. Auto Photo Sheet



Left radius cap



Right radius cap missing

RAC Adjustments, Inc. Auto Photo Sheet



Interior side posts



Right side interior

RAC Adjustments, Inc. Auto Photo Sheet



Door frame



Door frame

RAC Adjustments, Inc. Auto Photo Sheet



Right side interior



Right side interior

Date: 11/ 1/2022 09:20 AM
 Estimate ID: ddd4407
 Estimate Version: 0
 Committed
 Profile ID: * Madison

ALL SUPPLEMENTS MUST BE PRE-APPROVED IN WRITING PRIOR TO BEING PERFORMED .

RAC Adjustments, Inc.

1740 S. Bell School Rd. Suite A, Cherry Valley, IL 61016
 (414) 242-0406
 Fax: (815) 349-1000
 Email: btate@racadj.com

Damage Assessed By: Brent Tate

Appraised For: James Bangen
 (608) 410-3662

Classification:

Type of Loss: Collision
 Date of Loss: 10/20/2022
 Deductible: 500.00
 File Number: 607519
 Claim Number: AP85223-1

Insured: Office Pro
 Owner: Office Pro
 Address: 1810 SUTLER AVE, BELOIT, WI 53511
 Telephone: Work Phone: (608) 531-6001 ext. 208

Mitchell Service: 910872

Description: 2017 Chassis Mounted Bed Dry Van
 Type/Component: Chassis Mounted Bed
 VIN: 1FDNF6DC7HDB10880
 OEM/ALT: A
 Color: White

Drive Train:
 License: 83170 WI
 Search Code: 2X60098

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	000012	BDY	REMOVE/REPLACE	R Radius Panel	0027928045	125.02 *	3.0
2	000014	BDY	REMOVE/REPLACE	R Corner Cap	116404	77.28 *	INC*
3	000015	BDY	REMOVE/REPLACE	L Corner Cap	116405	77.28 *	INC*
4	000252	BDY	REMOVE/REPLACE	Upr Radius Panel	04A02754-01	150.82 *	INC*
5	000119	BDY	REMOVE/REPLACE	R Side Door Door Frame	05S19835-06	165.19 *	14.1 #
6				This is in the rear of the body			
7	000037	BDY	REMOVE/REPLACE	R Ctr Side Panel	003005050	1,050.00 *	48.0* #
8				x8			
9	000040	BDY	REMOVE/REPLACE	R Upr Rail	002076570012	268.96 *	10.5
10	900500	BDY *	REMOVE/REPLACE	Rivets	BRV00312	125.00 *	0.0*
11	900500	BDY *	REMOVE/REPLACE	Decals	Sublet	1,000.00 *	0.0*
12	000059	BDY	REMOVE/REPLACE	R Side Door Door Frame	Side Service DoorKit	761.06 *	16.4
13				This is on the side of the body			
14				USTRailerParts.com			
15	000085	BDY	REMOVE/REPLACE	R Inr Sidewall 2@91.93	23100195	183.86 *	2.0 #
16	000087	BDY	REMOVE/INSTALL	R Upr Track	Existing		1.0 #r
17	000089	BDY	REMOVE/INSTALL	R Lwr Track	Existing		1.0 #r
18	900500	BDY *	REMOVE/REPLACE	R Side Post Starter J Channel	01201149-13	30.42 *	0.5*
19	000093	BDY	REMOVE/REPLACE	R Side Post 4@31.68	015201011A	126.72 *	2.0 #
20	000202	BDY	REMOVE/REPLACE	Roof Panel	07100648	680.07 *	21.0* #
21	900500	BDY *	REMOVE/REPLACE	Starter Roof Bow	07200143-04	34.79 *	1.3*

ESTIMATE RECALL NUMBER: 11/01/2022 09:20:41 ddd4407

Mitchell Data Version: OEM: SEP_22_V
 MAPP:SEP_22_V

Copyright (C) 1994 - 2022 Mitchell International
 All Rights Reserved

Page 1 of 3

Software Version: 7.1.242

WBM_Office Pro_00053

Date: 11/ 1/2022 09:20 AM
 Estimate ID: ddd4407
 Estimate Version: 0
 Committed
 Profile ID: * Madison

22	000113	BDY	REMOVE/REPLACE	Roof Reinforcement Bow 5@47.94	07200142-04	239.70	*	6.5	#
23	000255	BDY	REMOVE/REPLACE	Adhesive	** QUAL REPL PART	250.00	*	1.0	*
24	000045	BDY	REMOVE/REPLACE	Clearance Lamp Assembly	14201163	12.64	*	0.5	
25				Right Front Top					
26	000159	BDY	REMOVE/INSTALL	Rear Door Shell	Existing			5.1	#r
27	900500	BDY *	REMOVE/REPLACE	Rear Door Right Side Grab Handle	05200036-01	13.92	*	0.3	*
28	900500	BDY *	REMOVE/INSTALL	Rear Door Right Side Clearance Lights and Switch	Existing			1.0	*

* - Judgment Item
 # - Labor Note Applies
 r - CEG R&R Time Used For This Labor Operation

Estimate Totals

I. Labor Subtotals	Units	Rate	Add'l Labor Amount	Sublet Amount	Totals	II. Part Replacement Summary	Amount
Body	135.2	110.00	0.00	0.00	14,872.00 T	Taxable Parts	5,372.73
						Parts Adjustments	1,030.68
						Sales Tax @ 5.500%	352.19
						Total Replacement Parts Amount	6,755.60
Taxable Labor					14,872.00		
Labor Tax			@ 5.500 %		817.96		
Labor Summary	135.2				15,689.96		
III. Additional Costs					Amount	IV. Adjustments	Amount
Total Additional Costs					0.00	Insurance Deductible	500.00-
						Customer Responsibility	500.00-
						I. Total Labor:	15,689.96
						II. Total Replacement Parts:	6,755.60
						III. Total Additional Costs:	0.00
						Gross Total:	22,445.56
						IV. Total Adjustments:	500.00-
						Net Total:	21,945.56

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF CRASH PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THESE PARTS RATHER THAN THE MANUFACTURER OF YOUR VEHICLE.

Point(s) of Impact

1 Right Front Corner (P)

Insurance Co: WEST BEND MUTUAL INSURANCE COMPANY
 Telephone: (800) 236-5003
 (800) 236-5003
 Fax Phone: (000) 000-0000

ESTIMATE RECALL NUMBER: 11/01/2022 09:20:41 ddd4407

Mitchell Data Version: OEM: SEP_22_V
 MAPP:SEP_22_V

Copyright (C) 1994 - 2022 Mitchell International
 All Rights Reserved

Date: 11/ 1/2022 09:20 AM
Estimate ID: ddd4407
Estimate Version: 0
Committed
Profile ID: * Madison

Inspection Site: Office Pro
Address: 1810 Sutler Ave
Beloit, WI 53511
(608) 531-6001 ext. 208
Inspection Date: 10/27/2022

Body Shop: Morgan Truck Body
Address: 3100 E Morgan Way |
Janesville, WI 53546
Telephone: (800) 477-2244 ext. 4225
State Lic. No: 25-1151457
Email: Don.driscoll@morgancorp.com

PURSUANT TO SECTION 5.301 OF THE ILLINOIS MOTOR VEHICLE CODE, VEHICLE
REPAIRERS MUST BE LICENSED.
AUTHORIZATION TO REPAIR MUST COME FROM VEHICLE OWNER!
NO SUPPLEMENTS WITHOUT INSPECTION AND PRIOR APPROVAL!

ESTIMATE RECALL NUMBER: 11/01/2022 09:20:41 ddd4407

Mitchell Data Version: OEM: SEP_22_V
MAPP:SEP_22_V

Software Version: 7.1.242

Copyright (C) 1994 - 2022 Mitchell International
All Rights Reserved

Page 3 of 3

WBM_Office Pro_00055

From: "noreply@cccis.com" <noreply@cccis.com>
Date: 11/02/22 06:41:10 AM
To: "PCC Scan Center" <PCCScan@WBMI.com>
Subject: [External]Claim data attached for AP85223-1 from WEST BEND MUTUAL
INSURANCE COMPANY.
Attachments: InvoiceBill.pdf

Sender: COPELAND, TOM Message: The claim data you requested is attached, for claim
number: AP85223-1 from WEST BEND MUTUAL INSURANCE COMPANY. rac invoice
please pay Claim Reference ID: AP85223-1 Contact List Recipients: Priority: Normal



RAC Adjustments, Inc.
 1740 S Bell School Road
 Suite A
 Cherry Valley, IL 61016
 Phone: 815-968-7686
 Toll Free: 877-240-0180
 Fax: 815-633-5086
Tax ID #: 36-3694468

FINAL

West Bend Mutual Insurance Company
 1900 South 18th Avenue
 West Bend, WI 53095
ATTENTION: Bangen, James

INVOICE #: RAC - 607519-1
INVOICE DATE: 11/1/2022
INVOICE DUE DATE: 12/1/2022

CLAIM INFORMATION

INSURED: OFFICE PRO INC
INSURED POLICY #:
OUR FILE #: RAC - 607519
YOUR FILE #: AP85223-1

ADJUSTER: Tate, Brent
LOSS DATE: 10/20/2022
LOSS UNIT: Auto Appraisal

BILLABLE ITEMS

ITEM	DESCRIPTION	QTY	RATE	PRICE
Auto Fee Schedule	Auto Appraisal Per Fee Schedule	1	\$540.00	\$540.00
Auto Mileage		42.6	\$1.00	\$42.60
Auto Photo		8	\$1.00	\$8.00
Auto Telephone		0	\$1.00	\$0.00
Auto Clerical Admin	Auto Clerical	15	\$1.00	\$15.00
<i>EXPENSES</i>				\$0.00
SUBTOTAL:				\$605.60
TAX & FEES:				\$0.00
TOTAL:				\$605.60

Brent Tate

From: Darhower, Bobby <bobby.darhower@onewabash.com>
Sent: Monday, October 31, 2022 1:04 PM
To: Brent Tate; Parts
Subject: RE: Serial #SVA26103102
Attachments: Parts List.pdf

CAUTION: This email originated from outside of RAC Adjustments. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Please see below the part numbers you have listed don't match the Serial number tied to the VIN you have in your file.

Serial# H0103204

R Radius Panel
0027928045 – IA-7928A 6 1/4"CORNER RADIUS X102"WITHOUT PUNCHING - \$126.02 ea.

R Corner Cap SUP
116404 – CURBSIDE FRONT CORNER CAP - \$77.28 ea.

L Corner Cap SUP
116405 – STREETSIDE FRONT CORNER CAP - \$77.28 ea.

Upr Radius Panel SUP
04A02754-01 – .063 ALUMINUM WIND DEFLECTOR 21 1/2" X 88.25" - \$150.82 ea.

R Side Door Door Frame
Side door was not installed by us not sure what was used. Can't quote.
See below picture of truck before it left our plant.

R Ctr Side Panel
003005050 – .040 ALUMINUM PANEL 49" X 106 3/8" - \$131.25 ea.

R Upr Rail SUP
002076570012 – IA-7657 ROOF RAIL X 317" - \$10.18 a ft. x 26.42 ft per side.

R Side Door Door Frame

Side door was not installed by us not sure what was used. Can't quote.
See below picture of truck before it left our plant.

Rivets

BRV00312 – 3/16" X 3/8" SOLID BRAZED RIVET, SOFT - \$18.70 a lb., For side wall skins

R Inr Sidewall

23100195 – 7.9MM PLYWOOD 48" X 96" TRUCKLINER OVERLAY - \$91.93 ea.

R Side Post

01201149-13 – 18 GA GALVANIZED STEEL J-CHANNEL 5.028" X 101 1/2" - \$30.42 ea. starter post for side wall.
015201011A – 18 GA GALVANIZED STEEL Z-POST 3.58" X 106 3/8" - \$31.68 ea. intermediate side wall post

Rear corner post

05S19835-06 – 12GA GVNL STEEL CORNER POST 13 3/8" X 108 1/4" - \$165.19 ea.

Roof Panel

07100648 – GLASS BOARD .060 X 100" WIDE - \$3.14 a sf. x 216.58 sf.

Roof Reinforcement Bow

07200143-04 – 16GA GALVANIZED STEEL INSERT 3 7/8" X 93 7/8" - \$34.79 ea. plus 1 intermediate makes the starter roof bow
07200142-04 – 18GA GALVANIZED STEEL ROOFBOW 1.25" X 96 7/8" - \$47.94 ea. intermediate roof bows

Clearance Lamp Assembly

Which one??

14201163 – AMBER LED MARKER CLEARANCE PC RATED WITH A66GB - \$12.64 ea.
14201161 – RED LED MARKER CLEARANCE PC RATED WITH A66GB - \$12.19 ea.

Rear Door Right Side Grab Handle

05200036-01 - 12" MILL FINISH ALUMINUM GRAB HANDLE - \$13.92 ea.





Thank you,
Bobby Darhower
Parts Sales Representative

Wabash
2581 East Kercher Road
Goshen, IN 46528
O: 800-642-4889 Ext. 20178
F: 574-642-0082
parts@onewabash.com
onewabash.com/

\$15.00 min order. (shipping charges are excluded)

Please check out our parts and upfit catalog at:

<https://onewabash.com/old-site/brands/supreme/upfit-parts-service/truck-body-parts-and-upfit-store>

Wabash National Email Confidentiality Disclaimer and Notice: <https://onewabash.com/email-disclaimer>

From: Brent Tate <btate@racadj.com>
Sent: Monday, October 31, 2022 1:21 PM
To: Parts <Parts@onewabash.com>
Subject: Serial #SVA26103102

Hello,

I am looking for help obtaining part numbers and prices to complete an estimate on the attached Supreme Serial Number. Attached are a list of parts that I am looking for as well as photos of the damages body. I was able to obtain part numbers and prices for a few of the parts online but not all of them. Please let me know if you have any questions.

Thank you,

Brent Tate
Assistant Appraisal Manager
RAC Adjustments, Inc.
Cell (414) 242-0406
btate@racadj.com