

OFFICE OF THE CLERK-TREASURER

201 DELAFIELD STREET  
WAUKESHA, WISCONSIN 53188-3692  
TELEPHONE CLERK - 262/524-3550  
TELEPHONE TREASURER - 262/524-3850  
FAX 262/524-3888

Gina Kozlik, Clerk-Treasurer  
gkozlik@ci.waukesha.wi.us

September 19, 2018

TO: Keith Yahn, Finance

RE: Claim of: Zachary Danby  
307 Carriage Drive  
Waukesha, WI 53188

Date of Accident or Claim: September 13, 2018

Date City Served: Received in person September 18, 2018

The enclosed is being sent to you for your information and consideration.

Sincerely,

Sandee Policello  
Deputy Clerk/Treasurer

Cc: Clerk (original) / Finance / Attorney / WPRF (Forestry)



From: Zach Danby zach.danby@att.net  
Subject: claim  
Date: Sep 17, 2018 at 4:16:53 PM  
To: zach.danby@att.net

---



To who this may concern my name is Zachary Danby and I live at 307 carriage dr Waukesha WI. The purpose of this claim is because on Thursday September 13,2018 across the street at 300 carriage dr Waukesha WI around 11-1 o clock the tree service was grinding a tree down and they ended up hitting my car across the street and damaging the driver side passenger door I noticed it at 3 pm when went to get my car.

From: Dave Rauterberg drauterberg@waukesha-wi.gov  
Subject: Car Damage  
Date: Sep 17, 2018 at 3:38:23 PM  
To: zach.danby@att.net




Zach,

Attached is the claim instructions I told you about.

**David Rauterberg**

David Rauterberg  
City Forester  
Waukesha Park, Recreation & Forestry  
[262-650-2545](tel:262-650-2545)  
[drauterberg@waukesha-wi.gov](mailto:drauterberg@waukesha-wi.gov)

Notice: Please be aware that email sent to, or received from, the City of Waukesha should be presumed to be a public record, that it will be retained by the City as a public record, and will be subject to public disclosure under Wisconsin's open records law. If you are not the intended recipient of this email, please do not read it or forward it to another person, but notify the sender and then delete it.



**Rubina Medina**

---

**From:** Zach <zach.danby@att.net>  
**Sent:** Tuesday, September 18, 2018 2:43 PM  
**To:** Rubina Medina  
**Subject:** Fwd:

First picture is we're my car was parked

Sent from my iPhone

Begin forwarded message:

**From:** Zach <zach.danby@att.net>  
**Date:** September 17, 2018 at 5:37:29 PM CDT  
**To:** zach.danby@att.net







Sent from my iPhone



### Mander Collision & Glass, Inc.

1604 Manhattan Dr., Waukesha, WI 53186  
Phone: (262) 446-0655  
FAX: (262) 446-0650

Workfile ID: cd1f679f  
Federal ID: 41-2000478  
State ID: 036-0000106494-04  
Resale Number: 456-0000106494-03

### Preliminary Estimate

---

**Customer: Danby, Zachary**

Written By: John Streblow

Insured: Danby, Zachary  
Type of Loss:  
Point of Impact: 08 Left Qtr Post (Left Side)

Policy #:  
Date of Loss:

Claim #: N/A  
Days to Repair: 0

**Owner:**  
Danby, Zachary  
307 Carnegie Dr.  
Waukesha, WI 53188  
(414) 217-4937 Cell

**Inspection Location:**  
Mander Collision & Glass, Inc.  
1604 Manhattan Dr.  
Waukesha, WI 53186  
Repair Facility  
(262) 446-0655 Day

**Insurance Company:**  
N/A

---

### VEHICLE

2018 HYUN Santa Fe Sport Automatic AWD 4D UTV 4-2.4L Gasoline Gasoline Direct Injection

VIN: 5NMZUDLB3JH056919 Interior Color: Mileage In: Vehicle Out:  
License: Exterior Color: Mileage Out:  
State: Production Date: Condition: Job #:

---

#### TRANSMISSION

Automatic Transmission  
4 Wheel Drive

#### POWER

Power Steering  
Power Brakes  
Power Windows  
Power Locks  
Power Mirrors

#### DECOR

Dual Mirrors  
Privacy Glass  
Console/Storage  
Overhead Console  
Wood Interior Trim

#### CONVENIENCE

Air Conditioning  
Intermittent Wipers  
Tilt Wheel  
Cruise Control  
Rear Defogger  
Keyless Entry  
Alarm  
Message Center  
Steering Wheel Touch Controls  
Rear Window Wiper  
Telescopic Wheel  
Backup Camera w/Parking Sensors

#### RADIO

AM Radio

#### FM Radio

Stereo  
Search/Seek  
CD Player  
Auxiliary Audio Connection

#### SAFETY

Drivers Side Air Bag  
Passenger Air Bag  
Anti-Lock Brakes (4)  
4 Wheel Disc Brakes  
Traction Control  
Stability Control  
Front Side Impact Air Bags  
Head/Curtain Air Bags  
Hands Free Device

#### SEATS

Cloth Seats  
Bucket Seats  
Reclining/Lounge Seats

#### WHEELS

Aluminum/Alloy Wheels

#### PAINT

Clear Coat Paint

#### OTHER

Rear Spoiler

#### TRUCK

Power Trunk/Gate Release

**Preliminary Estimate**

**Customer: Danby, Zachary**

2018 HYUN Santa Fe Sport Automatic AWD 4D UTV 4-2.4L Gasoline Gasoline Direct Injection

| Line             | Oper | Description                               | Part Number | Qty | Extended Price \$ | Labor      | Paint      |
|------------------|------|-------------------------------------------|-------------|-----|-------------------|------------|------------|
| 1                |      | <b>REAR DOOR</b>                          |             |     |                   |            |            |
| 2                | *    | Rpr LT Outer panel                        |             |     |                   | 3.0        | 2.1        |
| 3                |      | Add for Clear Coat                        |             |     |                   |            | 0.8        |
| 4                | R&I  | LT Belt molding                           |             |     |                   | 0.3        |            |
| 5                | R&I  | LT Handle, outside                        |             |     |                   | 0.4        |            |
| 6                | R&I  | LT R&I trim panel                         |             |     |                   | 0.4        |            |
| 7                | R&I  | LT Side molding w/o two tone molding      |             |     |                   | 0.4        |            |
| 8                |      | <b>REAR LAMPS</b>                         |             |     |                   |            |            |
| 9                | R&I  | LT Tail lamp assy w/o LED                 |             |     |                   | 0.4        |            |
| 10               |      | <b>QUARTER PANEL</b>                      |             |     |                   |            |            |
| 11               | Blnd | LT Quarter panel                          |             |     |                   |            | 1.3        |
| 12               | R&I  | LT Quarter glass Hyundai                  |             |     |                   | 1.5        |            |
| 13               | R&I  | LT Qtr trim panel w/o premium audio beige |             |     |                   | 0.4        |            |
| 14               | #    | Adhesive kit                              |             | 1   | 15.00             |            |            |
| 15               | R&I  | LT Wheel opng midg                        |             |     |                   | 0.4        |            |
| 16               |      | <b>REAR BUMPER</b>                        |             |     |                   |            |            |
| 17               | R&I  | R&I bumper assy                           |             |     |                   | 1.7        |            |
| 18               | #    | Hazardous waste removal                   |             | 1   | 3.00              |            |            |
| 19               | #    | Cover car                                 |             | 1   | 5.00              |            |            |
| <b>SUBTOTALS</b> |      |                                           |             |     | <b>23.00</b>      | <b>8.9</b> | <b>4.2</b> |

**ESTIMATE TOTALS**

| Category           | Basis       | Rate         | Cost \$         |
|--------------------|-------------|--------------|-----------------|
| Parts              |             |              | 23.00           |
| Body Labor         | 8.9 hrs @   | \$ 60.00 /hr | 534.00          |
| Paint Labor        | 4.2 hrs @   | \$ 60.00 /hr | 252.00          |
| Paint Supplies     | 4.2 hrs @   | \$ 40.00 /hr | 168.00          |
| Subtotal           |             |              | 977.00          |
| Sales Tax          | \$ 977.00 @ | 5.1000 %     | 49.83           |
| <b>Grand Total</b> |             |              | <b>1,026.83</b> |

MOTOR VEHICLE REPAIR PRACTICES ARE REGULATED BY CHAPTER ATCP 132, WIS. ADM. CODE, ADMINISTERED BY THE BUREAU OF CONSUMER PROTECTION, WISCONSIN DEPT. OF AGRICULTURE, TRADE AND CONSUMER PROTECTION, P.O. BOX 8911, MADISON, WISCONSIN 53708-8911.

## Preliminary Estimate

---

**Customer: Danby, Zachary**

2018 HYUN Santa Fe Sport Automatic AWD 4D UTV 4-2.4L Gasoline Gasoline Direct Injection

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide ARR1063, CCC Data Date 9/14/2018, and potentially other third party sources of data; and (b) the parts presented are OEM-parts manufactured by the vehicles Original Equipment Manufacturer. OEM parts are available at OE/Vehicle dealerships. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships. OPT OEM or ALT OEM parts may reflect some specific, special, or unique pricing or discount. OPT OEM or ALT OEM parts may include "Blemished" parts provided by OEM's through OEM vehicle dealerships. Asterisk (\*) or Double Asterisk (\*\*) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2019 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

### SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

### SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

### OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Information Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.