

An aerial photograph of a river with a complex, braided channel system. The water is a deep teal color, and the exposed sandbars and gravel bars are a light tan color. A large white circle is centered over the image, containing text. To the left of the circle, there is a dashed teal line. To the bottom right of the circle, there is a solid blue circle.

# Spring Committee Recommendations Meeting 12-16-20

Action Items for repairs to be done  
on Waukesha Springs



# Goals

Educate the citizens of Waukesha on the historical value of the Springs and bring attention to what needs to be done to keep it alive. A regular maintenance schedule such as: Oiling locks, repairing signs, and keeping up with vandalism.

# Acme

- Replace missing stones with historical inventory at the city storage
- New Acme spring sign
- Review the agreement with current property owner before discussing landscaping
- Shooting for repairs to be finished by May 1<sup>st</sup>

# Buchner

- Add new historic two-sided sign

# Crystal Rock


- Needs venting installed to preserve integrity of spring basin

# Minniska

- Replace historical sign on Kensington Drive

# Silurian

- Basement electrical corroded (needs electrician to look at)
- Basement venting needs repairs as it is blocked off



We appreciate your time and  
hope to see these issues  
addressed.

The Waukesha Spring Committee

12/28/20